

JTB00537V2

# TECHNICAL BULLETIN

26 JAN 2017



© Jaguar Land Rover Limited

All rights reserved.

## INFORMATION

---

Changes are highlighted in blue

---

### SECTION:

415-00

---

### SUBJECT/CONCERN:

Buzzing Sound From Tweeter Speaker

---

### AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
F-TYPE (X152)	2015 Onwards	K07480 Onwards	Castle Bromwich	Coupe

---

**MARKETS:**

All

---

**CONDITION SUMMARY:****SITUATION:**

A Customer may express a concern of a buzzing sound coming from the tweeter speakers. **This version update has been issued due to a note being added to the condition summary.**

**CAUSE:**

Software issue. **Suggested Customer concern code - JQ5**

**NOTES:**

- Coupe vehicles only.
- Only applicable to vehicles fitted with Premium 700 watt systems.

**ACTION:**


Should a Customer express this concern, follow the service instruction below.

---


**TOOLS:**



117925



117925



---

**WARRANTY:**

**NOTE:**

DDW/WASP requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

**NOTES:**

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.
- DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Configure Amplifier Module	86.99.42	0.6	42	T2R12664

**NOTE:**

Normal Warranty procedures apply.

**SERVICE INSTRUCTION:**

---

**CAUTIONS:**

- A Jaguar Land Rover approved battery support unit must be connected to the vehicle battery during diagnosis/module programming.
- Make sure all ignition 'ON'/ignition 'OFF' requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.

**NOTE:**

A Jaguar Land Rover approved diagnostic tool must be loaded with DVD148.02 258 or later.

- 1 Connect the Jaguar Land Rover approved battery support unit to the vehicle battery.

---

- 2 Turn ignition 'ON' (engine not running).

---

- 3 Connect the Jaguar Land Rover approved diagnostic tool to the vehicle and begin a new session.

---

- 4 Follow the on-screen prompts, allowing the Jaguar Land Rover approved diagnostic tool to read the VIN and identify the vehicle and initiating the data collect sequence.

---

- 5 Select 'Diagnosis' from the Session Type screen.

---

- 6 Select the 'Selected Symptoms' tab, and then select:
  - Electrical - Information and entertainment system - Entertainment system - Audio - Audio sound quality poor.

---

- 7 Select 'Continue'.

---

- 8 Select the 'Recommendations' tab.

---

- 9 Select 'Run' to perform the 'Configure existing module - Audio amplifier module' option.

---

- 10 Follow all on-screen instructions to complete this task, make sure all Diagnostic Trouble Codes (DTC's) are cleared.

---

- 11 When all tasks are complete, select the 'Session' tab and then select the 'Close Session' option.

---

- 12 Disconnect the Jaguar Land Rover approved diagnostic tool and the Jaguar Land Rover approved battery support unit from the vehicle.