

JTB00495NAS1

TECHNICAL BULLETIN

06 JUN 2016



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION**SECTION:**

309-00B

SUBJECT/CONCERN:

Exhaust System Noise Reduction

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
F-TYPE (X152)	2014-2015	K00001-K22184	Castle Bromwich	V8 S/C 5.0L Petrol

MARKETS:

NAS

CONDITION SUMMARY:**SITUATION:**

The exhaust system noise may be reduced.

CAUSE:

This may be caused by incorrect software.

ACTION:


Should a customer express this concern, follow the Service Instruction below.

PARTS:

No Parts Required

TOOLS:**NOTE:**

This Active Bulletin will display a functional programming shortcut if accessed within a diagnostic session.



Jaguar Land Rover-approved diagnostic tool with latest DVD and Calibration File



Jaguar Land Rover-approved Midtronics battery power supply

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to JLR claims submission system to obtain the latest repair time.
- The JLR Claims Submission System requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Configure Existing Powertrain Control Module	86.99.26	0.2	42	C2D30319

NOTE:

Normal Warranty procedures apply.

SERVICE INSTRUCTION:

CAUTIONS:

- A Jaguar Land Rover-approved Midtronics battery power supply must be connected to the vehicle battery during diagnosis / module programming.
- Ensure all ignition ON/OFF requests are carried out; failure to perform these steps may cause damage to control modules in the vehicle.

NOTES:

- The Jaguar Land Rover-approved diagnostic tool must be loaded with DVD145.07 v.240 or later.
- Use DDW to check for Recall, Service Action, or Update Prior to Sale notice eligibility requiring a Powertrain Control Module (PCM) software update. If eligible, perform and claim the PCM update as per that program.

- 1 Connect the Jaguar Land Rover-approved Midtronics battery power supply to the vehicle battery.
- 2 Turn ignition ON (engine not running).
- 3 Connect the Jaguar Land Rover-approved diagnostic tool to the vehicle and begin a new session.
- 4 Follow the on-screen prompts, allowing the diagnostic tool to read the VIN, identify the vehicle, and initiating the data collect sequence.
- 5 Select '**Diagnosis**' from the Session Type screen.
- 6 Select the '**Selected Symptoms**' tab and then select:
 - **Powertrain - Engine system - Emissions - Exhaust noises**
- 7 Select '**continue**'.
- 8 Select the '**Recommendations**' tab and then select '**Run**' to perform the '**Configure existing module - Powertrain control module**' option.

- 9 Follow all on-screen instructions to complete this task, ensuring all Diagnostic Trouble Codes (DTC) are cleared.

- 10 When all tasks are complete, select the '**Session**' tab and then select the '**Close Session**' option.

- 11 Disconnect the diagnostic tool and battery power supply from the vehicle.