Events by distance





SAJWA6BC3F8K11450

Model: Jaguar X152 F-Type Session creation: Thu 02-May-2024 11:16 Session printed: Thu 02-May-2024 11:36
Current odometer: 45,012mi

	2,500mi	5,000mi	7,500mi	10,000mí	12,500mi	15,000mi	17,500mi	20,000mi	22,500mi	25,000m	i 27,500mi	30,000mi	32,500mi	35,000mi	37,500
		# # # #							1				1		
DTC	ECU	Distance ▼	Descr	iption							Status	Options		Relevan	ice
P0420-00	i - Event 8 PCM	44,961mi	Catalys	st System E	Efficiency B	elow Thresh	nold (Bank	1) - No sub	type informa	ation	i,	60		100%	
U0001-87	i - Event 7 IPC	44,902mi	High S	peed CAN	Communic	ation Bus - I	Missing me	ssage			E	10		====	
U2101-00	i - Event 6 HCMB	44,826mi	Contro	ol Module C	Configuration	n Incompati	ble - No su	b type infor	mation			60			
□ 43,085m B1A56-11	i - Event 5 ACM	43,086mi	Antenn	na - Circuit s	short to gro	und						6			\neg
⊟ 41,892m B1086-00	i - Event 4 HVAC	41,892mi	Air Dis	stribution Da	amper Moto	or - No sub t	ype inform	ation				(ia			\exists
□ 41,172m U0140-00	i - Event 3 ATCM	41,173mi	Lost C	Communical	tion With Be	ody Control	Module - N	lo sub type i	nformation		ij	(fo			
U0121-00	ATCM	41,142mi	type in	nformation				(ABS) Conti			i,	100			
U0294-00 U012A-00	ATCM	41,142mi 41,142mi	inform	ation				'A" - No sub			ÿ ÿ ÿ				
B13C5-92 U0447-00	GWM PCM	41,142mi 41,142mi		15	20	ance or inco		ation type informa	ition		is is				
-⊟ 101mi - E U0140-08	Event 1 ——	101mi	Lost Co	ommunicatio	on With Bo	dy Control N	Module - Bu	ıs signal/me	ssage failur	es	Č,	66			
Unknowr	Events —	mi	Invalid	Data Recei	ved From 0	Cruise Contr	ol Module	- Signal belo	w allowable	e range					

Model

F-TYPE / X152

Model Year

2015

Module

Engine Control Module

DTC

P0420-00

Description

Catalyst System Efficiency Below Threshold Bank 1 - No sub type

information

Possible Causes

Monitor description. Oxygen storage capacity of the catalyst too low

- · Exhaust system leakage
- Catalytic converter failed, caused by lean combustion
- Catalytic converter failed, caused by misfire
- Catalytic converter failed, caused by excessive oil consumption
- Catalytic converter failed, caused by contaminated fuel

Action

- Using the Jaguar Land Rover approved diagnostic equipment, check powertrain control module, for related Diagnostic Trouble Code(s) and refer to the relevant DTC index
- Check exhaust system for leakage
- Refer to the relevant sections of the workshop manual and check the induction system for air leaks
- Refer to the relevant sections of the workshop manual and check the ignition system for causes of misfire
- Refer to the relevant sections of the workshop manual and complete oil consumption checks
- Confirm with the customer that the correct fuel has been used