06/11/2021 13:09:40

PAGE 1

SERIAL NO. : SAJWA82C48TH26200

R.O DATE : 09/10/2014

R.O TYPE : S

MILEAGE : 91728

JOB NUMBER : 1 OPERATION 10JAZ06

OP. DESC. CHECK ENGINE LIGHT

COMPLAINT : CUSTOMER STATES CHECK ENGINE LIGHT ON

ENGINE OVERHEATED AND NOW MISSES AND LIGHT FLASHES

: VERIFIED COMPLAINT

CORRECTION : DIAGNOSTICS REVEALED MISFIRE CODES ON CYLINDERS #1, #2, #3, #4, #5, #6 AND #7. REMOVED SPARK PLUGS AND FOUND THEM FOULED. REPLACED SPARK PLUGS, ENGINE STILL MISFIRING ON CYLINDER #7. COMPLETED CYLINDER COMPRESSION TEST, DRY AND WET. COMPRESSION READINGS ARE AS FOLLOWS: #1-120PSI, #2-130 PSI, #3-125PSI, #4-120PSI, #5-130PSI, #6-140PSI, #7-0PSI AND #8-110 PSI. BORE-SCOPED CYLINDER #7 AND FOUND THE INTAKE VALVE BENT AND STICKING DOWN INTO THE COMBUSTION CHAMBER. ENGINE HAS JUMPED TIMING. REPLACED ENGINE ASSEMBLY SWAPPED IN NEW SPARK PLUGS AND REPLACED ONE LEAKING SUPER-CHARGER CHARGED AIR COOLING HOSE. VERIFIED ENGINE PERFORMANCE IS NOMINAL AFTER REPAIRS. INSTALLED WITH USED ENGINE ASSY PER CUSTOMER REQUEST.

ASC EXTENDED WARRANTY AUTH#942329831

ENGINE HBAS A 6 MONTH PART WARRANTY ONLY

JOB NUMBER : 2 OPERATION 01JAZ100K

OP. DESC. 100K SERVICE

SALE TYPE : C

COMPLAINT : CUSTOMER REQUEST 100,000 MILE MAINTENANCE SERVICE

CORRECTION : 100,000 MILE SERVICE COMPLETED

NO ADDITIONAL LABOR CHARGES DUE TO ENGINE REPLACEMENT

JOB NUMBER : 3 OPERATION 01JAZ

OP. DESC. MISC OPERATION

SALE TYPE : C TECHNICIAN NO(S). 0424

COMPLAINT : BALANCE BOTH FRT WHEELS FOR EXCESS VIBRATION

CORRECTION : RE-BALANCED BOTH FRONT WHEELS. MOVED LEFT FRONT WHEEL TO

THE REAR DUE TO DAMAGED WHEEL

JOB NUMBER : 4 OPERATION 51JAZ15

OP. DESC. POWER ACCESSORIES

SALE TYPE : C TECHNICIAN NO(S).

COMPLAINT : CUSTOMER STATES W/WIPERS ONLY WORK ON HIGH

: VERIFIED COMPLAINT

CORRECTION : CUSTOMER PROVIDED ESTIMATE FOR REPAIRS, CUSTOMER DECLINED

REPAIRS AT THIS TIME.

R.O NO. : 398330

R.O DATE : 01/07/2014

R.O TYPE : S

MILEAGE: 80392

HISTORY LISTING

06/11/2021

13:09:40

COMPLAINT : CUSTOMER STATES AIR SUSPENSION FAULT MESSAGE DISPLAYED,

FRONT END IS DOWN

: INSPECTED AND FOUND LF AIR STRUT LEAKING

RECOMMENDED BOTH FRONT AIR STRUTS TO BE REPLACED

CORRECTION : REPLACED BOTH FRONT AIR STRUTS, VERIFIED REPAIR

R.O NO. : 385376 R.O DATE : 04/05/2013

R.O TYPE : S

MILEAGE : 68229

ADVISOR NO. : 342926

JOB NUMBER : 1 OPERATION 51JAZ01

OP. DESC. BODY ELECT CONCERN

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES WHEN YOU POP TRUNK TO UNLOCK, IT WILL

POP BUT NOT FULLY UNLATCH

CAUSE

: VERIFIED CONCERN

CORRECTION : CHECKED THE TRUNK LATCH, MOTOR NOT FULLY UNLATCHING MECHANISM CORRECTLY. NEEDS NEW TRUNK LATCH ASSEMBLY.

REPLACED THE TRUNK LATCH ASSEMBLY. VERIFIED TRUNK

WORKING CORRECTLY

JOB NUMBER : 2 OPERATION 51JAZ

OP. DESC. BODY ELECTRICAL

SALE TYPE : C

TECHNICIAN NO(S) 8588

COMPLAINT : CUSTOMER STATES ONE KEY FOB WILL NOT UNLOCK VEHICLE.

SECOND REMOTE ALL FUNCTIONS WORK

CAUSE

: VERIFIED CONCERN

CORRECTION : CHECK THE FOBS THE UNLOCK BOTTON INSIDE ONE OF THE FOBS

IS DAMAGED. NEEDS A NEW FOB TO WORK CORRECTLY. ESTIMATE

PROVIDED, CUSTOMER DECLINED

JOB NUMBER: 3 OPERATION 60JAZ12

OP. DESC. VISORS

SALE TYPE : C TECHNICIAN NO(S). 8588 COMPLAINT : RIGHT FRONT SUNVISOR IS COMING LOOSE

CAUSE : VERIFIED CONCERN

CORRECTION : THE RIGHT SIDE VISOR MOUNT CAME LOOSE AND TAB BROKEN OFF

IN BACK. INSTALLED WITH SEALER, TIGHTEN SCREW TO

SPECIFICATION. VERIFIED REPAIR

COMMENTS : DROP BOX

RECOMMEND : RECOMMEND REPLACING ONE KEY FOR \$365

RECOMMEND DIAGNOSING COOLANT LEAK- VEHICLE CAME IN LOW ON COOLANT RECOMMEND DIAGNOSING WHY SIDEMARKER LAMPS AND ONE LICENSE PLATE

BULB DOES NOT WORK

R.O NO. : 379020

R.O DATE : 11/12/2012

R.O TYPE : S

MILEAGE : 63512

ADVISOR NO. : 342926

JOB NUMBER : 1 OPERATION 01JAZ190

OP. DESC. BALANCE WHEELS/TIRES

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES RIGHT REAR WHEEL IS CRACKED, OTHERS

HISTORY LISTING

13:09:40

MAY BE BENT. PLEASE BALANCE AND CHECK FOR STRAIGHTNESS

CAUSE : WE USE ONLY THE BEST EQUIPMENT TO ENSURE THE LEAST AMOUNT

OF ROLLING RESISTANCE. WE USE THE "JAGUAR" OF SHOP EQUIPMENT

CORRECTION : CHECKED ALL WHEELS FOR STRAIGHTNESS, RIGHT REAR WHEEL

IS CRACKED, CHECKED WITH VENDOR THEY ARE UNABLE TO

REPAIR. CUSTOMER PICKED UP WHEEL AND HAD REPAIRED.

THE LEFT FRONT WHEEL HAS A SLIGHT BEND TO IT, MAY NOT BE

ABLE TO FEEL WHILE DRIVING. CUSTOMER DELEIVERED REPAIRED

WHEEL BACK. INSTALLED NEW TPMS SEAL KIT, MOUNTED AND BALANCED TIRE. TEST DROVE VEHICLE TO ENSURE TPMS

LAMP WENT OUT, REMOUNTED SPARE TO TRUNK, VERIFIED REPAIR

JOB NUMBER : 2 OPERATION 70JAZ01

OP. DESC. SUBLET REPAIR

PAGE 3

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSOTMER REQUESTS TO REPAIR RIGHT REAR WHEEL

CORRECTION : WE ARE UNABLE TO SEND OUT FOR REPAIR, CUSTOMER HAD

WHEEL REPAIRED

R.O NO. : 378199 R.O DATE : 10/24/2012

R.O TYPE : S

MILEAGE : 378199

ADVISOR NO. : 342926

JOB NUMBER : 1 OPERATION 60JAZ08

OP. DESC. CONSOLE

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES CENTER CONSOLE WILL NOT STAY LATCHED

\$90 .5

CAUSE : VERIFIED CONCERN

CORRECTION : CONSOLE LATCH BROKEN, REPLACED LATCH AND VERIFIED REPAIR

JOB NUMBER : 2 OPERATION 01JAZ221

OP. DESC. WIPER BLADES

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES WINDSHIELD WASHER RESEVOIR WILL NOT HOLD

FLUID \$110 .5

CAUSE : VERIFIED CONCERN

CORRECTION : FILLER TOP NECK BROKEN, REPLACED TOP FILLER NECK, VERIFIED

REPAIR. TOPPED OFF WINDSHIELD WASHER FLUID

COMMENTS : BOB

R.O NO. : 377880

R.O DATE : 10/17/2012

R.O TYPE : S

MILEAGE : 62402

ADVISOR NO. : 342926

JOB NUMBER : 1 OPERATION 60JAZ08

OP. DESC. CONSOLE

SALE TYPE : I TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES WOOD TRIM PEELING ROOF CONSOLE NEAR

SUNGLASS HOLDER

CAUSE : VERFIED CONCERN

CORRECTION : CHECK WOOD TRIM AND GLUE TRIM TO HOLDER. THE TAPE SHOULD

STAY ON TILL 3:00

HISTORY LISTING

13:09:40

INTERNAL CHARGE AS OVERHEAD CONSOLE TOOK SEVERAL MONTHS TO COME IN ORIGINALLY AND WOOD HAS BEEN REGLUED ONCE BEFORE.

JOB NUMBER : 2 OPERATION 60JAZ01

OP. DESC. INT TRIM CONCERN

PAGE 4

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES CENTER CONSOLE WILL NOT STAY LATCHED

: VERIFIED CONCERN

CORRECTION : ESTIMATE PROVIDED FOR REPAIRS, STOCK ORDERED PARTS

JOB NUMBER: 3 OPERATION 01JAZ221

OP. DESC. WIPER BLADES

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES WINDSHIELD WASHER RESEVOIR WILL NOT HOLD

FLUTD

CAUSE : VERIFIED CONCERN

CORRECTION : WINDSHIELD WASHER FLUID FILLER NECK IS SOURCE OF LEAK,

STOCK ORDERED PARTS

JOB NUMBER: 4 OPERATION 01JAZ222

OP. DESC. EXTERIOR LIGHTING

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER STATES LEFT FRONT PILOT BULB OUT

CAUSE : VERIFIED CONCERN

CORRECTION : REPLACE THE LEFT HEAD LAMP RUNNING LAMP BULB , LAMP NOW

WORKING

COMMENTS :

R.O NO. : 370921

R.O DATE : 05/23/2012

R.O TYPE : S

MILEAGE : 56316

ADVISOR NO. : 342926

JOB NUMBER : 1 OPERATION 60JAZ

OP. DESC. INTERIOR TRIM

SALE TYPE : C TECHNICIAN NO(S). 6657

COMPLAINT : CUSTOMER STATES TRIM PANEL UNDER GLOVE BOX IS RIPPED,

BEN HAS PARTS IN STOCK

: OWNER'S REQUEST

CORRECTION : REPLACE TRIM PANEL, RETEST, OK

JOB NUMBER : 2 OPERATION 60JAZ08

OP. DESC. CONSOLE

SALE TYPE : I TECHNICIAN NO(S). 6657

COMPLAINT : CUSTOMER STATES ROOF CONSOLE COMING APART, SEE HISTORY

CAUSE : STICK TAPE LOOSE

CORRECTION : REMOVE ROOF CONSOLE WOOD AND REATTACHED WITH STRONGER

ADHESIVE

INTERNAL CHARGE AS ROOF CONSOLE REPLACED UNDER WARRANTY

RO 365133 1/1/2012

COMMENTS : WAIT

HISTORY LISTING 06/11/2021

PAGE 5 13:09:40

R.O NO. : 365133 R.O DATE : 01/11/2012 R.O TYPE : S

MILEAGE : 49711 ADVISOR NO. : 342926

JOB NUMBER: 1 OPERATION 60JAZ01 OP. DESC. INT TRIM CONCERN

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : CUST STATES INTERIOR WOOD AT OVERHEAD CONSOLE WONT STAY UP

: VERIFY OWNER'S COMPLAINT CAUSE CORRECTION : CAUSE: WEAK RETAINING EARS

CORRECTION: REPLACE ROOF CONSOLE & RETEST, OK

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO.

365133-A 761369 365133-A 101010

COMMENTS : WAIT

R.O NO. : 355613 R.O DATE : 06/08/2011 R.O TYPE : S

MILEAGE : 39048 ADVISOR NO. : 7740

JOB NUMBER : 1 OPERATION 01JAZ OP DESC. MISC OPERATION

SALE TYPE : W TECHNICIAN NO(S) . 6657

COMPLAINT : CUST STATES INTERIOR WOOD AT OVERHEAD CONSOLE WONT STAY UP

CORRECTION : PART CAME IN WRONG, HAD TO REORDER 6/8/11

R.O NO. : 354083 R.O DATE : 05/05/2011

R.O TYPE : S

MILEAGE : 37337

ADVISOR NO. : 7740

JOB NUMBER : 1 OPERATION 01JAZ196 OP DESC. ROTATE AND BALANCE

SALE TYPE : C TECHNICIAN NO(S). 6657 COMPLAINT : ROTATE AND BALANCE

: CUSTOMER REQUEST ROTATE AND BALANCE CAUSE

JOB NUMBER : 2 OPERATION 01JAZ OP. DESC. MISC OPERATION

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : CUST STATES WOOD SUROUND FELL OFF OVERHEAD CONSOLE

PART IS IN GLOVE BOX

CAUSE : VERIFY OWNER'S COMPLAINT

CORRECTION : ORDER OVERHEAD CONSOLE 5/5/11, TRIM NOT AVAILABLE SEPARETE

JOB NUMBER : 3 OPERATION 01JAZZ1 OP. DESC. MISC OPERATION

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : CUST STATES TRIM ON EACH SIDE OF SUNROOF FALLS DOWN

WILL NOT STAY ATACHED

CAUSE : VERIFY OWNER'S COMPLAINT

CORRECTION : CAUSE: SIDE TRIM ON SUNROOF MECH. LOOSE

CORRECTION: REFIT & SECURE SIDE TRIM ON SUNROOF, RETEST, OK

HISTORY LISTING

PAGE 6 13:09:40 _______

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO.

354083-C 768204

JOB NUMBER : 4 OPERATION 60JAZ01 OP. DESC. INT TRIM CONCERN

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : HEADLINER LOOSE ABOVE DRIVERS HEAD

CAUSE : VERIFY OWNER'S COMPLAINT

CORRECTION : CAUSE: RETAINING CLIPS AROUND SUNROOF OPENING IN HEADLINER

HAS BROKENRETAINING CLIPS

CORRECTION: PARTICAL R&R OF HEADLINER TO GAIN ACCESS TO CLIP

REPLACE CLIPS & SECURE, RETEST, OK

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO.

354083-D 769524

R.O NO. : 347572 R.O DATE : 12/08/2010 R.O TYPE : S

MILEAGE : 30786 ADVISOR NO. : 7740

JOB NUMBER : 1 OPERATION 01JAZ30K OP. DESC. 30K SERVICE

SALE TYPE : C TECHNICIAN NO(S). 941553

COMPLAINT : CUSTOMER REQUEST 30,000 MILE MAINTENANCE SERVICE

CORRECTION : 30,000 MILE SERVICE COMPLETED

JOB NUMBER : 2 OPERATION 01JAZROTBAL OP. DESC. ROTATE AND BALANCE

SALE TYPE : C TECHNICIAN NO(S). 941553

COMPLAINT : CUSTOMER REQUEST ROTATE AND BALANCE

CAUSE : TIME AND OR MILEAGE

CORRECTION : COMPLETED ROTATE AND BALANCE

R.O NO. : 341126 R.O DATE : 07/14/2010 R.O TYPE : S MILEAGE : 23116

ADVISOR NO. : 7740

JOB NUMBER : 1 OPERATION 01JAZ20K OP. DESC. 20K SERVICE

SALE TYPE : C TECHNICIAN NO(S). 6657

COMPLAINT : CUSTOMER REQUEST 20,000 MILE MAINTENANCE SERVICE

CAUSE : MAINTENANCE SERVICE

CORRECTION : MAINTENANCE SERVICE COMPLETED

JOB NUMBER : 2 OPERATION 60JAZ OP. DESC. INTERIOR TRIM

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : CHROME TRIME AT CENTER CONSOLE COMMING OFF

CAUSE : VERIFY OWNER'S COMPLAINT

CORRECTION : VERIFIED. FOUND RETAINER EAR WEAK. CRACKED. DEFECT IN MATERI

CORRECTION : REPAIR PROCEDURE, REPLACE CONSOLE LIP CHROME

OPEN LEVER, RETEST, OK

HISTORY LISTING

13:09:40

PAGE 7

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO.

341126-B 769502

JOB NUMBER ; 3 OPERATION 60JAZ10

OP. DESC. SEATS

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : PASS SEAT TRIM AT VENT COMMING LOOSE

: VERIFY OWNER'S COMPLAINT

CORRECTION : CAUSE : PASSENGER'S SIDE CONSOLE VENT IS DISPLACED

CORRECTION : REPAIR PROCEDURE, REINSTALL VENT & SECURE,

RETEST, OK

JOB NUMBER : 4 OPERATION 61JAZ01

OP. DESC. EXT TRIM CONCERN

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : DRIVER REAR TAIL LIGHT TRIM FELL OFF

: VERIFY OWNER'S COMPLAINT

CORRECTION : CAUSE : MISSING

CORRECTION : REPAIR PROCEDURE, CHROME NOT AVAILABLE SEPARATE

REPLACE LEFT TAIL LAMP ASM, RETEST, OK

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO.

341126-D 864146

JOB NUMBER : 5 OPERATION 51JAZ01

OP. DESC. BODY ELECT CONCERN

SALE TYPE : W TECHNICIAN NO(S). 6657

COMPLAINT : CUST STATES AT TIMES WHEN ATTEMPTING TO USE NAV SCREEN WILL

TURN GRAY AND HAVE NO RESPONCE MUST RECYCLE KEY

: UNABLE TO VERIFY COMPLAINT

CORRECTION : REPAIR PROCEDURE, CHECK FOR CODE IN NAV. SCREEN, NONE, HAS

LATEST SOFEWARE LEVEL, SHOWED PAUL, NO FURTHER ACTION TAKEN

JOB NUMBER : 6 OPERATION 17JAZ

OP. DESC. RENTAL CAR

SALE TYPE : W TECHNICIAN NO(S). 6657 COMPLAINT : RENTAL VEHICLE PROVIDED CORRECTION : RENTAL VEHICLE PROVIDED

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO.

341126-F

JOB NUMBER : 7 OPERATION 01JAZ134

OP. DESC. REPLACE REAR BRAKES

SALE TYPE : C TECHNICIAN NO(S). 6657

COMPLAINT : FOUND REAR BRAKE PADS IN NEED OF REPLACEMENT

CAUSE : REAR FRICTIONS WORN

CORRECTION : REPLACE REAR PADS AND ROTORS

-----R.O NO. : 335735

R.O DATE : 03/10/2010

R.O TYPE : S

MILEAGE : 16684

ADVISOR NO. : 7740

OP. DESC. OIL CHANGE

JOB NUMBER : 1 OPERATION 01JAZ00 SALE TYPE : C TECHNICIAN NO(S). 8588

HISTORY LISTING

PAGE 8 -----

COMPLAINT : CUSTOMER REQUEST OIL CHANGE

CAUSE : CHANGE OIL AND FILTER

CHECK FLUIDS

CORRECTION : OIL CHANGE COMPLETED

JOB NUMBER : 2 OPERATION 01JAZROTBAL OP. DESC. ROTATE AND BALANCE

SALE TYPE : C TECHNICIAN NO(S). 8588

COMPLAINT : CUSTOMER REQUEST ROTATE AND BALANCE

CAUSE : TIME AND OR MILEAGE

CORRECTION : COMPLETED ROTATE AND BALANCE

NOTE THE RIGHT SIDE RIMS ARE BENT , WORST IS ON THE REAR.

R.O NO. : 330533 R.O DATE : 10/28/2009

R.O TYPE : S

MILEAGE : 10680

ADVISOR NO. : 7740

JOB NUMBER : 1 OPERATION 51JAZ

OP DESC, BODY ELECTRICAL

SALE TYPE : W TECHNICIAN NO(S). 8588 06209

COMPLAINT : CUST STATES VEHICLE GETS NO VOLUME FROM RADIO CD OR BLUETOOT

CAUSE : CHECK CODES-U2602(21), U2602(10), U2603 AND U2604 STORED-LOST

COMMUNICATION ON D2B NETWORK

CORRECTION : TESTED POWER AND GROUND TO AMP-OK-SWAPPED AMP FROM DONOR CAP NO CHANGE-TESTED NAV, SAT RADIO AND REAR ICE SYSTEM-NAV WORKS REAR ICE INOP AND SAT RADIO NOT COMMING UP AS OPTION ON BAND SELECTION-TEST POWER AND GROUND TO GATEWAY MODULE-OK-CHECK FIBER OPTIC CABLES TO AMP AND GATEWAY MODULE-OK-CALLED TECH LINE-WAS TOLD TO TEST SAT RADIO MODULE-REMOVED UPPER AND LOWER REAR SEATS-TEST POWER AND GROUND TO SAT RADIO MODULE-OK-MODULE NOT RECOGNIZED IN MODULE LIST IN IDS(FOR CODES) -REMOVED COMPONENT STACK IN TRUNK-TESTED POWERS AND GROUNDS-ALL OK-CHECKED FIBER OPTIC CABLES-FOUND PHONE MODULE WAS LIT WITH FIBER OPTICS UNPLUGGED-PERFORMED HARD RESET ON PHONE MODULE-LIGHT WENT OUT-RECONNECT ALL WIRING AND FIBER OPTIC CABLES-RETEST-SYSTEM WORKING-CLEARED CODES FROM ALL MODULES-ALL SYSTEMS CAME BACK-REAR ICE AND SAT RADIO WORKING NORMALY REASSEMBLE REAR SEATS AND TRUNK-RETEST ALL SYSTEMS-ALL OK-CALLED TECH LINE WITH RESULTS AND CLOSED CASE

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO

865003

865010 330533-A 869999 330533-A

330533-A

869942 866200

330533-A 330533-A

JOB NUMBER : 2 OPERATION 17JAZ

330533-A

330533-A 101010 869996

OP. DESC. RENTAL CAR

SALE TYPE : W TECHNICIAN NO(S) 06209

COMPLAINT : RENTAL VEHICLE PROVIDED

CORRECTION : RENTAL VEHICLE PROVIDED

WARRANTY : CLAIM NO. OPERATION NO. CLAIM NO. OPERATION NO 06/11/2021 HISTORY LISTING PAGE 9 13:09:40

330533-B

R.O NO. : 328939 R.O DATE : 09/21/2009 R.O TYPE : S

MILEAGE : 8479 ADVISOR NO. : 7740

JOB NUMBER : 1 OPERATION 51JAZ01 OP. DESC. BODY ELECT CONCERN

SALE TYPE : C TECHNICIAN NO(S). 06209

COMPLAINT : CUST STATES PASS SIDE HEADREST VIDEO SCREEN DOES NOT COME ON

CAUSE : UNABLE TO DUPLICATE-ALL WORKING PROPERLY WHEN TESTED