

**S-TYPE**

DATE 07/02

S303-09

SERVICE

TECHNICAL BULLETIN

MIL Illuminated – 3.0 L V6 –
False Flagging of DTC P1383 or P1388 –
Reprogram PCM

MODEL 2000-02 MY
S-TYPE 3.0 L
VIN L00001-M44997

Issue:

Some 2000-01 MY S-TYPE vehicles may experience illumination of the MIL with DTCs P1383 or P1388 (over retarded camshaft timing) stored.

To eliminate the false flagging of DTCs P1383 and P1388, the Powertrain Control Module (PCM) should be re-programmed using WDS software release JTP759/14 or later.

Note: The PCM is described as the ECM when using WDS.

When entering the ECM re-configuration section the user will be prompted to determine the engine serial number of the vehicle.

If the first six digits of the engine number are outside the specified serial number range (103981*** to 127908***) the user will be allowed through to re-calibrate the vehicle PCM with a standard set of calibrations.

If the engine serial number falls within the given range the system will automatically divert to a more aggressive set of calibrations.

Action:

In case of a customer complaint of the above condition on a 2000-01 MY S-TYPE vehicle within the above VIN range, follow the workshop procedure outlined below.

PCM REPROGRAMMING PROCEDURE

Note: The engine number is located on the bar code label on the engine front cover (Illustration 1) or on the left-hand side of the engine bedplate (Illustration 2). Position the vehicle on a lift as needed to gain access.




ILLUSTRATION 1




ILLUSTRATION 2

1. Open hood and cover fenders.

Note: Use WDS software JTP 759/14 or later.

2. Position the WDS alongside vehicle, switch 'ON' Portable Test Unit (PTU) and allow software to load.
3. Connect the PTU to the vehicle data link connector (DLC) via diagnostic cable.
4. Enter the VIN and navigate to content model screen, select engine system, and then go to DTC monitor.
5. Read engine DTCs, if any stored clear from memory.

Note: If any DTCs are stored, determine the fault and carry out on a separate Warranty claim.




ILLUSTRATION 3

6. Navigate to configuration main menu; select and run 're-configure existing ECM'.

Note: While WDS is re-programming PCM, apply generic update label (JJM 998499/20) alongside the VCATS label in the trunk with revised part number (from table below), and date of re-configuration added to label (Illustration 3).

VIN L00001 to L86901:

Trans.	Engine	Market	Calibration Type (file to be selected*)	New ID Number
Auto	3.0L V6	North America	XDAF3B4	XR8A 12A650 NBL
			XDAF3BZ	XR8A 12A650 NBK
Auto	3.0L V6	Mexico (and Europe)	XDAF3C4	XR8A 12A650 NCK
			XDAF3CZ	XR8A 12A650 NCJ

VIN L86902 to M44997:

Trans.	Engine	Market	Calibration Type (file to be selected*)	New ID Number
Auto	3.0L V6	North America	XDAF3BY	1R8A 12A650 DBH
			XDAF3B2	1R8A 12A650 DBG
Auto	3.0L V6	Mexico	XDAF3S4	1R8A 12A650 GSG
			XDAF3S2	1R8A 12A650 GSF

* based on engine number

Note: These calibration files offer two separate improvements: the shift quality improvement (Technical Bulletin S307-07) and the rectification of the false flagging of DTC P1383 or P1388 (Technical Bulletin S303-09). If a vehicle exhibits both concerns, it is not necessary to perform both bulletins, since both improvements will result when performing either bulletin.

7. After the reprogramming of the PCM is complete, switch 'OFF' PTU, disconnect and return WDS to original location.
8. Remove fender protector covers and close hood.

AUTHORIZED MODIFICATION LABEL

JAGUAR **AUTHORIZED MODIFICATIONS**

THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:

REFLASH PER TSB S303-09/S307-07

WRITE IN DESCRIPTION

WRITE IN DATE

WRITE IN DEALER NUMBER

THESE MODIFICATIONS HAVE BEEN APPROVED, AS APPROPRIATE.

DEALER NUMBER: [] DATE: []

CHANGE AUTHORITY: JAGUAR PLC CAMPAIGN

PRINTED IN U.S.A.

ILLUSTRATION 4

9. Enter your dealer number and the date on the Authorized Modification Label as shown (Illustration 4). Write in "Reflash per TSB S303-09/S307-07." Apply the label to the left B-post below the door striker plate. Be sure to apply the clear protective sheet over the label.

Parts Information:

To obtain blank Authorized Modification Labels, refer to Administration Bulletin 6-94 titled "Availability of Service Action and Recall Authorized Modification Labels/stickers."

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Generic update label	JJM 998499/20	1

Warranty Information:

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

Description	SRO	Time	Causal Part Number	Causal Part Description
V6 Camshaft timing issue - service fix	86 92 93	0.5 hrs.	XR8 14085 XR8 18437	PCM VIN L00001-L86901 PCM VIN L86902-M44997