2003 S-Type 3.0L

P0057 Heater Control Circuit

Bank 2 Sensor 2

(Downstream O2 Sensor LHS)

Sensor Location

Not bad to access

Best with a lift

Doable with ramps – but you must decide whether you need to be on back or belly before you slide under; no rolling-over in-situ

Tools:

Something larger than the 21mm open-end spanner I have


7/8" Open-end "may" work – I became convinced in my case it wouldn't and went so far as to change into a clean stained shirt for a trip to town to obtain a 22mm or 23mm – whatever it takes – guessing 22mm.

I suddenly remembered I had a large adjustable wrench on the pegboard for tractor-work

Gave it a try and broke the senor loose nicely.

But I get ahead of myself:

You needn't bother with loosening the sensor until you find the other end of the wiring and disconnect it.



Wiring Connector

It's hiding behind the "710" filter alongside the upstream O2 sensor connector

Maybe, if you have a lift and long, very skinny hands – you can disconnect it with the 710 filter in-place. I didn't even try.

So plan to do a 710 change while you are at it.



Ahhh....THAT'S better

Downstream sensor connector is on the right in this pic, upstream on the left. The pigtail and connector from each sensor is at the top, car harness/connector at the bottom

A study of the connector on your replacement sensor will reveal the mounting feature and locking feature to you.

I probed the cavity denoted by the arrow with a tiny screwdriver very lightly and "SNAP!" the locking tab broke off and fell in my face

No harm/no foul as it was part of the failed sensor assy.

Gave a sharp tug downward on the car harness connector and they separated

Then I probed the (front – though it appears as the "back" in this pic) side of the connector whilst pulling down to dislodge it from the mounting bracket



The Hard Part is Over

Note the wire-routing as you remove it and you can return to slide #1 and proceed with the Sensor removal steps.

Not certain, but I believe I read in JTIS that the fixing torque for the sensor is 40 nm. No matter, my torque-wrench is a ratchet and useless in this application.

I put the new one on "good-n-firm" with the 7/8" open-end, after a liberal application of the included anti-sieze compound



Parts

I used **Denso 234-4798 Oxygen Sensor** obtained from Amazon for the sum of \$50.60

http://www.amazon.com/gp/product/ B000PWWJAM/ref=oh details o03 s0 0 i00?ie=UTF8&psc=1

Cleared the code and took it out for a post-maintenance-check-ride and the panel stayed "clean and green"



