



# TECHNICAL BULLETIN

S307-14

12/2003

## Subject

**Surge During Warm up at 40mph to 60mph**

**Model: S-TYPE Vehicles N/A**

**Year: 2002.5 to 2004**

**VIN M45255 to N01600**

**Model: S-TYPE Vehicles SC**

**Year: 2002.5 Onwards**

**VIN M45255 Onwards**

**Section: 307-01**

**Automatic Transmission/Transaxle**

## Summary

S307-14: This Technical Bulletin has been issued to address a customer concern of a surge in excess of 150rpm during engine warm up, at a temperature of 30°C to 50°C and at a vehicle speed in the region of 40mph (64.3kph) to 60mph (96.5kph).

## Action

Should a customer express a concern, the Transmission Control Module (TCM) should be re-configured using the Worldwide Diagnostic System (WDS) with software release JTP 759/27 or later. Follow the workshop procedure outlined below.

**Note: Due to some homologation laws this action will need to be monitored. For this reason a new coded access route will be available on WDS for this Technical Bulletin.**

## Workshop Procedure

- 1 Position WDS alongside vehicle, switch Portable Test Unit (PTU) 'ON' and allow software to load.

**Note: Ensure WDS is loaded with software release JTP 759/27 or later.**

- 2 Connect PTU to vehicle using diagnostic cable.
- 3 Enter vehicle VIN and navigate to configuration main menu.
- 4 Navigate through the configuration of existing TCM application to screen that states 'Select the access route you require for this vehicle'

**Note: When carrying out this Technical Bulletin only, select the 'Coded Access' route.**

- 5 Record the ten digit request code displayed on the PTU screen, then continue to the next screen.
- 6 Contact Dealer Technical Support (DTS) to obtain the ten digit access code.

**Note: You will need to inform DTS of the dealer details, the request code and details of the vehicle.**

- 7 Enter the ten digit access code and continue through the application following on screen prompts.
- 8 After re-configuration of TCM is complete, switch 'OFF' PTU, disconnect from vehicle and return WDS to original location.

**Warranty Information**

<b>Description</b>	<b>Vehicle</b>	<b>SRO</b>	<b>Labor Time Allowance</b>	<b>Causal Part</b>
Re-configure TCM through coded access route	All	86 93 27	0.4 Hours	C2C 6718