

A CUSTOMER STATES THAT THERE IS A CREAKING NOISE COMING FROM REAR END.

LOW SPEEDS, OVER BUMPS AND DRIVEWAY ENTRANCE.

CAUSE: INEFFECTIVE REAR STRUT MOUNT BUSHES/SSM54477/ 'ST' TO ISOLATE NOISE.

643034 REAR SHOCK ABSORBER/SPRING UPPER MOUNT -
VEHICLE SET - RENEW

173 WJ4

2 C2Z15891 ISOLATOR-SPRING

601000 SHOP TIME

173 WJ4

101010 DRIVE IN-OUT

173 W97

(N/C)
(N/C)
(N/C)
(N/C)

FC: 42

PART#: C2Z15891

COUNT: 2

CLAIM TYPE: 01

AUTH CODE:

VW*N51

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 0.00

34602 noisy rear upper strut mounts road test car and found excessive creaking from rear suspension over bumps. raised car and removed rear spring bolts to adjust rear suspension to duplicate noise on lift--no noises.. refit and applied chassis ears to rear strut towers and rear lower control arms. road test car and found noise from rear struts. performed ssm54477 and replaced both rear strut tower mount bushings--noisy over bumps. road test car after replace---all good

B STEERING COLOM WHEN GOING UP AND DOWN MAKES A GRINDING, TICKING NOISE WHEN MOVING UP AND DOWN//CHECK AND ADVISE

CAUSE: INTERNAL STEERING COLUMN BINDING.

869999 DIAGNOSTIC ALLOWANCE

173 WJ4

1 C2P23933 COLUMN-STEERING

(N/C)
(N/C)

<p><i>For Your Convenience</i></p> <p>Service Dept. Hours</p> <p>Monday thru Friday</p> <p>7:00 AM to 6:00 PM</p>	NOTICE TO CONSUMER:		DESCRIPTION	TOTALS
	I acknowledge notice and oral approval of any additional customer or warranty work performed and/or increase in the original estimate price. I also acknowledge and approve all repairs as itemized and/or receipt of vehicle. I also acknowledge receipt of additional consumer warranty and service information contained in the Parts & Service Warranty Disclaimer.		LABOR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES	
			TOTAL CHARGES	
			LESS INSURANCE	
			SALES TAX	
			PLEASE PAY THIS AMOUNT	

CUSTOMER COPY