DTC	Condition	Possible Causes	Action
P0171	Right-hand cylinders combustion too lean	 Air intake leak between mass air flow (MAF) sensor and cylinder head Fuel filter/system restriction Fuel injector restriction Fuel rail pressure (FRP) sensor fault (low fuel pressure) Low fuel pump output HO2S/catalyst monitor sensor harness wiring condition fault EFT sensor fault (low fuel temperature) Mass air flow (MAF) sensor fault (low intake air flow) Exhaust leak (before catalyst) ECM receiving incorrect signal from one or more of the following sensors; ECT, MAF*, IAT, fuel rail temperature 	For intake system, <<303- 12>> For fuel injector, Fuel Injectors (18.10.02) For fuel filter and pump, <<310-01>> For FRP sensor circuit tests, GO to Pinpoint Test G206886p2. . For HO2S/Catalyst monitor sensor tests, <<303-14>> For exhaust system, <<309-00>> For sensor tests, <<303-14>> * If this DTC is flagged, pay particular attention to the MAF sensor.
P0172	Right-hand cylinders combustion too rich	 Engine misfire Restricted air filter Leaking fuel injector(s) FRP sensor failure (high fuel pressure) EFT sensor fault (high fuel temperature) MAF sensor fault (high intake air flow) HO2S/catalyst monitor sensor harness wiring condition fault ECM receiving incorrect signal from one or more of the following sensors; ECT, MAF, IAT, FRP, EFT. 	Check for "misfire detected" DTCs in this section; For intake system, <<303-12>> For fuel injector, Fuel Injectors (18.10.02) For FRP sensor circuit tests, GO to Pinpoint Test G206886p2. . For other sensor tests, <<303-14>>
P0174	Left-hand cylinders combustion too lean	 Air intake leak between MAF sensor and cylinder head Fuel filter/system restriction 	For intake system, <<303- 12>> For fuel injectors, Fuel Injectors (18.10.02) For fuel filter, pump and

Diagnostic Trouble Code (DTC) index

		 Fuel injector restriction FRP sensor failure (low fuel pressure) Low fuel pump output HO2S/catalyst monitor sensor harness wiring condition fault EFT sensor fault (low fuel temperature) Mass air flow (MAF) sensor fault (low intake air flow) Exhaust leak (before catalyst) ECM receiving incorrect signal from one or more of the following sensors; ECT, MAF*, IAT, FRP, EFT, TP.
P0175	Left-hand cylinders combustion too rich	 Engine misfire Restricted air filter Leaking fuel injector(s) FRP sensor failure (high fuel pressure) ECM receiving incorrect signal from one or more of the following sensors; ECT, MAF, IAT, fuel rail pressure, fuel rail temperature Check for "misfire detected" DTCs in this section. For intake system, <<303-12>> For fuel injectors, Fuel Injectors (18.10.02) For FRP sensor tests, GO to Pinpoint Test G206886p2. For other sensor tests, <<<303-14>>
P0191	Fuel rail pressure (FRP) sensor circuit range/performance	 Fuel filter/system restriction Fuel system leak Incorrect fuel pump output FRP sensor to ECM sensing circuit; high resistance, open circuit, short circuit to high voltage FRP sensor to splice in sensor supply circuit; high resistance, open circuit FRP sensor to splice in sensor ground circuit; high resistance, open circuit, short circuit to ground, short circuit to high voltage FRP sensor failure
P0192	Fuel rail pressure (FRP) sensor circuit low voltage	 FRP sensor disconnected FRP sensor to ECM sensing For FRP sensor tests, GO to Pinpoint Test G206886p2.