
Reference	SSM73047
Models	F-TYPE / X152
Title	X152 - Clutch Kit Improvement - Updated Part
Category	Driveline
Last modified	07-Feb-2017 00:00:00
Symptom	506000 Clutch Concerns

Content**Issue**

Premature clutch wear and poor clutch pedal feel

Cause

Clutch slippage between gear changes at high engine speed/torque.

Action

New parts are now available to order though JEPC for this issue.

F - Type (X152) **New part number T2R25681** original part number T2R21165

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.