

Brief notes and technical information tips about Jaguar products

Jaguar Model Designations

Information: Some Jaguar literature may refer to a vehicle by its model code designation. Refer to the following list for VIN and model years for each code designation.

Years	Model	VIN Range	Model code
1997-2002	XK8 – XKR	001001 – A30644	X100
2003-2004	XK8 – XKR	A30645 - A40264	X103
2005-current	XK8 – XKR	A40265 – current	X104
2000-2002	S-TYPE	L00600 - M44997	X200
2003-2004	S-TYPE	M44998 - N13089	X202
2005-current	S-TYPE	N13089 – current	X204
1995-1997	XJ8 – XJR	720001 – 812255	X300
1995-1997	XJ LWB	720001 – 812255	X330
1998-2003	XJ8 – XJR	812256 – F59525	X308
1998-2003	XJ LWB	812256 – F59525	X338
2004-current	XJ8 – XJR	G00442 – current	X350
2005-current	XJ LWB	G34528 – current	X355
2002-2003	X-TYPE	C00344 - D56272	X400
2004-current	X-TYPE	D56272 – current	X404

Note: A small number of early production cars may fall outside the VIN ranges for their respective models. If there is a question, consult DDW for actual model year.

Models: X-TYPE All MY

Procedure: Steering wheel angle sensor (SWS) replacement

<u>Information:</u> Prior to ordering an SWS, check the attachment of the coupling at the base of the upper column. A bolted on coupling indicates that the SWS can be removed from the column and replaced. If the coupler is riveted to the base of the upper column, the entire column must be replaced as an assembly.

Equipment: PDU Software

<u>Information</u>: The final versions of software were released for PDU in 2001 as stated in Administration Bulletin 1-125, which should be printed and posted on PDU base station for convenient reference. Due to Service Action S514, S479 should *never* be used to program a customer's car. The software for S479 should only be used to recover an ECM after a WDS reflash failed and then the ECM *must* be programmed with S514 software.

Software issue JTP 626/7, released 02/00: 1990-96 MY XJS / 1990-94 MY Sedan Range Software issue JTP 627/10, released 01/01: 1995-2001 MY XJ Series / 1997-2001 MY XK8 / 2000-2001 MY S-TYPE

Note: Jaguar no longer supports PDU for repair, parts, or software. Existing software should be copied and the master kept in a safe place. Any malfunctioning cables should be repaired and not discarded.

Send your tip suggestion for TechLines to rhagema2@jaguar.com (FAX to TechLines Editor at 201 818 8478)

February TSB Summary:

Service Bulletin Listing

Number	Technical Bulletin Title	Model	VIN	Date
419-17	Driver or Passenger Seat Module (DSM/PSM) Lid - Damaged or Loose - Lids Available Separately	XK	VIN A11051-ON	01/05
S307-18	Automatic Transmission Remove/Install - New Workshop Procedure - Revised Labor Times	2003 MY-ON S-TYPE	M44998-ON	01/05
S308-01	Manual Transmission Remove/Install - New Workshop Procedure - Revised Labor Times	2003 MY-ON S-TYPE	M44998-ON	01/05
XJ303-06	Cooling System - Draining, Filling and Bleeding - SRO Time Revision	XJ range	G00001-ON	01/05
XJ419-04	Battery Discharged After Vehicle Left Standing - Check Module Reset Count - Diagnosis/Repair Procedure	XJ	G00001-ON	01/05
XT206-R957	Parking Brake Lever - Replacement - Recall R957	2002-03 MY X-TYPE	C00294-D03128 See Bulletin for specific VIN	01/05
XT501-27	Power Seats - Loss of Function - Seat Motors Available Separately	2002 MY-ON X-TYPE	C00001-ON	01/05

Number	Parts Bulletin Title	Model	VIN	Date
A-31CAN	Jaguar Canada Warranty Parts and Core Parts Returns - Revised Process	All	All	01/05
R-13	Occupant Seat Sensor Kit - Generation 2	2004 MY-on XJ range	G12878-ON	12/04
R-14	Occupant Seat Sensor Kit - Generation 2	2005 MY-on X-TYPE	E19616-ON	12/04
U-13	Trunk Badges	2002-03 MY V8 XJ	F40032-F59525	12/04

Number	Administration Bulletin Title	Model	Date
3-194USA	UPS Consignee Billing Shipments - Temporary Change	All	01/05
3-195USA	Scheduled Maintenance Program - 2005 MY Vehicles	All	01/05
6-121CAN	2005 Jaguar Service Loaner/Convenience Program (SLCP) - Canadian Market	All	01/05
7-28USA	Recall Campaign - Parking Brake Lever Replacement - Manual Transmission Vehicles Only - RECALL R957	2002-03 MY X-TYPE	01/05
7-29CAN	Brake Fluid Reservoir Warning Obscured - New Brake Fluid Warning Label - RECALL R171	2005 MY S- TYPE N13089- N35567	01/05
7-29USA	Brake Fluid Reservoir Warning Obscured - New Brake Fluid Warning Label - RECALL R171	2005 MY S- TYPE N13089- N35567	01/05

FAQ'S		
Subject	Model	Date
FAQ 19241 - V8 4.2L & 3.5L Oil leak	S TYPE / XJ / XK	05-Jan- 2005
FAQ 19281 - 2005 S-TYPE Fuel Tanks Concerns	S TYPE	05-Jan- 2005
FAQ 19361 - XJ (new) non start - fuel pump problem	XJ	11-Jan- 2005
FAQ 19401 - New XJ V60 Phone Diagram & Pin Data	XJ	12-Jan- 2005
FAQ 19421 - X-Type Final Drive - Pinion Seal Leak	X TYPE	13-Jan- 2005
FAQ 19441 - Wiring harness repairs	X TYPE / S TYPE / XJ / XK	14-Jan- 2005
FAQ 19521 - Air Suspension Compressor Relay - C2303	XJ	19-Jan- 2005
FAQ 19581 - XK Sports Mode Switch Sticking	XK	24-Jan- 2005
FAQ 19601 - S415-02 Clarification-Unnecessary Repair	S TYPE	24-Jan- 2005
FAQ 19761 - Fuel door actuator	S TYPE	27-Jan- 2005
FAQ 19801 - Light Connectors	X TYPE	31-Jan- 2005

What WDS software are you running? The current release is CD 36. Missing a Bulletin? You can find it on GTR.

<u>Note:</u> When contacting the Technical HelpLine, please be sure to have your pre-call worksheet filled out prior to contacting us. The more information you have at hand will shorten the time necessary to discuss and rectify your concerns