
Reference	SSM45450
Models	XJ / X351
Title	New Jaguar XJ Panoramic roof blind Re-tensioning procedure
Category	Body
Last modified	06-Sep-2010 00:00:00
Symptom	105000 Roof Options
Attachments	X351 Pan Roof blind retensioning.pdf (X351 Pan Roof blind retensioning.pdf)
Content	<p><u>Issue:</u> The panoramic roof blind will not roll up when retracting, return spring de-tensioned</p> <p><u>Cause:</u> Locking pin not inserted into blind during removal to prevent return spring de-tensioning</p> <p><u>Action:</u> Follow the procedure in the attached document to re-tension blind.</p>