

ACFGJF_Uby9i.exe

Patch_File_Instructions-_NAS_Telephone_System.pdf

Reference SSM8121

X200 / S-TYPE

Models X400 / X-TYPE

X350 / XJ

Title Configure `B` Mesage -Telephone
Fittment

Category Diagnostic Software Hardware

Last modified 25-Oct-2007 00:00:00

Symptom 000102 WDS Patch / Update

Issue:

A WDS software error has been identified where by the option for the North American Telephone System is omitted from the WDS menu structure. This will result in a message warning being displayed on the message center that reads "Config B".

Please be advised that when installing a Jaguar Accessory Telephone, you must configure the telephone "PSE" module. This action will enable the vehicles in car entertainment system to recognize a telephone system is present. Failure to carryout this step will result in the message "Config "B " being displayed on the message center.

ACTION:

As an interim containment a patch file has been created which will resolve this issue as well as update your WDS machine to include this new software. The files are located below under attachments. This file contains the downloading /installing instructions and the second contains the actual patch file. Please note these files are auto executing and will place the files in the appropriate directories.