

JST 1818


Fig. 1

XJS (1993 Model Year) SECURITY SYSTEM

ADDENDUM to Fitting Instructions

LED and Valet Switch Installation

With the introduction of the driver's airbag module at 1993 MY, the locations of the LED warning light and valet switch have changed.



JST 1819

Fig. 2

Valet Switch

Undo and remove the three screws securing the steering column lower cowl.

Remove the cowl.

Mark the position for the valet switch as detailed in Fig 1.

Cut out the aperture for the switch and deburr.

Note: Switch situated adjacent to ignition lock, inboard.