| | | | | |
|---|---|---|---|---|
| Feb-06 | 14500 | Warranty repair on oil supply problem to variable valve timing apparatus | $ | 0 |
| Mar-10 | 71000 | Idler pulley replaced due to squeak; serpentine belt replaced; air filter replaced | $ | 306 |
| Nov-10 | 77500 | New heater control assembly in dash "Blend doors", air volume n temp uneven side to side | $ | 2,600 |
| Oct-12 | 100000 | New speaker driver side on dash | $ | 100 |
| Dec-13 | 111,000 | Heater not working on driver's side AGAIN. New heater core installed. | $ | 1,800 |
| | | Also, computer said some oil was being used on start-up so they serviced the | | |
| | | throttle body and replaced the PCV valve. | | |
| | | TOTAL: | **$** | **4,806** |