TECHNICAL SERVICE BULLETIN
No.JTB00047/2007
18 June 2007

Circulate to:	Service Manager	Parts Manager	Warranty Administrator	Service Reception	Technicians		

Subject/Concern:	Puddle Lamps Inoperative After S856	
Model:		
The New XK	VIN Range: B00001-B05068	

Markets:	All
Section:	100-01A

Summary

Following the S856 software update, the door puddle lamps cease functioning.

Cause: On vehicles prior to VIN B05068, the parameter for puddle warning lamps within the CCF was not required to be set.

Action: If the puddle lamps fail to operate following the S856 update, reset the vehicle configuration parameter using Integrated Diagnostic System (IDS). Follow the Service Instruction outlined below

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

Labor Time		
Operation Description	**Operation No.**	**Time**
Reset the vehicle configuration parameter	86.99.61	0.2 hours
Repair/Claim Coding		
Causal Part:	C2P 15083	
ACES Condition Code:	42	

Service Instruction

1. ⚠️ **This procedure requires IDS DVD107 Patch File 6 software or later.**

• Make sure the doors are shut or latched before you download the vehicle configuration file.

Connect an approved battery charger/power supply to the vehicle.

2. Connect IDS to the vehicle and begin a new diagnostic session, by entering the correct VIN for the current vehicle.

3. When prompted 'Do you wish to read diagnostic trouble codes?', select 'No' and then press 'tick' to continue.

4. When the 'Content Model' is displayed select 'Vehicle Configuration' tab.

5. Select from the menu 'Vehicle Configuration'.

6. Select 'Display and/or modify the configuration file data'. From the drop down menu and then press 'tick' to continue.

7. Please read battery voltage warning. When you have read the warning and the battery voltage is above the minimum limit, then press the green tick to proceed.

8. The CCF parameter data page will be displayed listing all parameters.

9. Find the parameter for outer mirror puddle lamps and then select 'puddle lamps are fitted'.

10. An operator question box will appear asking 'Do you wish to download the vehicle configuration file', press the green tick to proceed.

11. If the vehicle configuration file does not download successfully, lock and unlock the doors, and then try and download the vehicle configuration file again.

12. When the task is completed, exit the current session.

13. Disconnect IDS and the battery charger/power supply.