

Service History 2001 Jaguar XJ8
Purchased 11/4/2003 for \$26250 (New Car placed in Service 8/30/2001)
Grand Total We have paid for Repairs/Maintenance Todate 15223.91

Date	Mileage	Description of Work	Cost	Total
12/2/2010	94004	tirerack.com - 4 new Michelin X-Ice Xi2 Ice and snow tires	524.12	
		Promotion - Tirerack/Michelin prepaid credit card of \$70 for buy	-70.00	
		Wallingford Tire - winter tire change over	95.53	549.65
9/14/2010	91826	Eriksson Industries - rebuild our existing transmission (replace freewheel, valve body main pressure regulator, valve body other plate, spag, forward drum, rebuild existing torque converter, fill transmission with fluid and dyno test the transmission)	2432.70	
		Scott's Labor to remove and install transmission	550.00	
		Langan Volkswagen - 3) 1 liter transmission fluid bottles	60.42	3043.12
7/17/2010	90758	Jaguar dealer parts dept- Oil & Filter & coolant + hose	125.00	
		Scott - Replace cam chains & tensioners & Water Pump plus plus the Engine Oil & Filter	750.00	
7/14/2010		Fedex Returned Tools	40.28	
7/13/2010		Christopher's Napa NJ - Refunded Deposit on Tools	-424.00	
6/29/2010		Christopher's Napa NJ		
		Cam chains & tensioners kit & water pump/& Tools Deposit	1222.95	
6/26/2010		Jaguar of Hartford - Troubleshooting Engine problem	139.67	
6/23/2010	90758	Scott inspected Engine trouble - Restricted Performance	100.00	1953.90
4/9/2010		Advance auto parts - fuse assortment - for car lighter	15.89	15.89
12/17/2009		Scott Installed new rotors and pads on front and rear	100.00	
12/6/2009		Auto Parts Warehouse - Front & Rear rotors and pads	438.75	538.75
12/4/2009	86931	Hartford Jaguar - 6 month service - Oil change with oil filter Oil \$43.15, oil filter \$17.95, Labor \$28.00	71.15	
		Pressure checked water pump and added coolant	61.00	
		15% discount on Labor & Parts plus Jag discount on Labor	-30.67	
		Enviornmental & shop charge \$5.00 - 6% sales tax on total	11.39	
		also replaced wiper blade (warranteed - no charge)		112.87
		Need rotors & pads for front & rear- Est for rear \$705.00		
11/5/2009	85800	Walmart - New battery - maxx-49n \$80.00 plus tax	84.80	
		Jim install the battery		84.80
6/4/2009	78709	Darien Jaguar - Oil Change (Motorcraft) with Oil filter \$60.95	54.92	
		Replace wiper inserts \$22.70	20.45	
		Brake Flush service \$113.50 + 4.00 (shop supplies)	106.50	181.87
11/21/2008	73273	Jaguar Southington -Oil Change with Oil filter \$31.95; Labor \$39.50 Also adjusted emergency brakes \$15.00	75.74	
			15.90	91.64
5/2/2008	67676	Jaguar Southington - 70M mile service(Labor \$128) Oil Change with Oil filter \$31.95; Rubber windshield wiper		
			\$22.66	193.57
4/23/2008	67445	Jaguar Southington - Replace Fuel Pump & Lead-Link Mercury Warantee Paid for Replacement and Fuel Pump cost of \$185 plus Labor of \$350 - a total \$535		

	We paid for the Lead-Link wire	135.84	135.84
12/5/2007	64537 Jaguar Southington -Oil Change with Oil filter \$31.95; Oil Change with Oil filter \$31.95; Rubber windshield wiper \$22.66 plus Labor \$19 Tax on CD Player Jaguar Southington - refunded the tax Replace 10 disks CD Player -Mercury Insurance Extended Warrantee Claim (\$160 for CD player after exchange & \$95 labor - total was \$255)	75.74 44.16 15.30	135.20 -15.30
11/13/2007	Cheshire Gulf Service Station - Detailing		189.00
5/16/2007	57923 Jaguar Southington - 60M mile service (Labor \$208.50) Oil Change with Oil filter \$61.95 (Labor \$30 - .5 hrs) Air Filter element \$60.07 (Labor \$17 -.2 hrs) Pump out Brake Fluid & replace it \$101.12 (Labor \$85 - 1.0 hrs) Replace Fuel Filter \$76.82 (Labor \$42.50 - .5 hrs) Throttlebody service \$25.50 all Labor - .3 hrs Lubricate door hinges & sun roof tracks n/c Clear fuel door drain n/c Clean part load breather \$8.50 all labor	347.87	347.87
5/15/2007	57888 Costco - Snow tires removed/Reg Tires installed	25.44	25.44
10/17/2006	53426 Costco - Purchased 4) Michelin X-ice snow tires	449.40	449.90
10/10/2006	Jagbits - New Front Signal Light assembly & Rear Tail Light assembly	337.11	337.11
9/5/2006	Towne Fair Tire -Flat repair	14.73	14.73
9/1/2006	Cliff Jacobs Wheel Repair Repair bent rim	100.00	100.00
8/30/2006	Knucklebusters Used Auto Parts Replacement Fog Lamp (Len was broken) Wrong Part - Returned 10/10/2006	95.00	95.00 -80.00
8/24/2006	Cliff Jacobs Wheel Repair weld in patch on spare tire rim	85.00	85.00
7/19/2006	50587 Oil Change with Oil Filter & replace rubber wiper blade & Balance/rotate tires	187.91	187.91
5/2/2006	48000 Town Fair Tires - Snow Tires Changeover package - includes wheel alignment	94.34	94.34
1/17/2006	45205 Stephen Jaguar - 28 Isolators for valve covers	83.11	83.11
1/17/2006	45205 Stephen Jaguar - Schedule 8:00am Replace Valve Cover Gaskets -Extended Warrantee Claim (\$449.35)	0.00	0.00
1/12/2006	45130 Stephen Jaguar - Lub & Oil change Note: Valve Cover Gaskets are leaking Also Burning Smell when heater is on	75.74 0.00	75.74

Service could not duplicate this condition

11/3/2005	43000	Town Fair Tires - Snow Tires Changeover	42.40	42.40
11/3/2005	43000	Anderson Tire - Emission Test & Tire Repair	33.78	33.78
8/15/2005	40249	Replaced Water Pump	0.00	0.00
7/27/2005	39670	Stephen Jaguar - Labor - Replace Front Brake pads & rotors	147.87	
7/22/2005		Tire Rack - Front Brake pads (\$62) & Brembo Rotors (\$61 x 2) plus shipping \$24.02	208.02	355.89
7/25/2005		Purchased Extended Service Warrantee -	2250.00	2250.00
7/20/2005	39531	Lub & Oil change 40000 mile service	0.00	
		Replaced Fuel Cap	0.00	
		Replaced J-Gate Module (Shifter Housing Gasket)	0.00	
		Replaced Left Front door rubberseal	0.00	
		Sunroof - Repair Link Assy & Reinstall	0.00	
		Note: Found Front Pads & Rotors need replacement -Est \$736		
		Front Control Arms Bushings cracked		
		Replaced front bushings & Align Front	0.00	
		Replace Rear Pinion Seal	0.00	
3/22/2005	34802	Winter Lub & Inspection service		
		Lub & Oil change with 24 point inspect	136.44	
		Replaced Left Front Door rubber seal	0.00	
		Replaced SOP Sensor - Outside Temp	0.00	
		Replaced Coolant Level Sensor	0.00	136.44
11/16/2004	31306	Replaced both Front doors rubberseals	0.00	
7/20/2004	27948	Lub & Oil change 30000 mile service	0.00	
		Replaced outside air temp sensor	0.00	0.00
7/15/2004	27500	Snow Tire Changeover to regular tires	59.65	
		Repaired Flat Tire	3.95	63.60
4/2/2004	24432	Lub & Oil change with 24 point inspect	89.38	
		sunroof -refit & align lift arms clean & lub		
		roof tracks repair spring clips	0.00	89.38
1/8/2004	22200	Replaced Windshield Wiper Arm	38.69	38.69
12/12/2003	21900	Purchased 4 used Pirelli Snow Tires	100.00	
		Town Fair Tires - Put on Snow Tires	42.19	142.19
12/10/2003		Est Date - Replace Front Windshield Insurance Claim paid for it	0.00	0.00
12/2/2003	21857	Lub & Oil change	57.80	
		Replaced Windshield washer hose	0.00	57.80
11/14/2003	20600	Town Fair Tire - 4 Pirelli p6000 Tires	596.00	
		" - 4 wheel Alignment	44.00	640.00

11/10/2003	Sales Tax	1596.00	
	Auction Fees	350.00	
	Auction Commission	200.00	2146.00
11/5/2003	RodeWay Inn - lodging Auction		33.30
11/3/2003	CarFax		24.99
11/1/2003	Train Tickets to Auction		142.50