



autologic

Autologic Quick Test Report

VIN **SAJWA03V051N19907**
 Manufacturer **Jaguar**
 Vehicle **S-TYPE X204**
 Year **2005**
 Autologic information **Autologic Serial Number A008874**
Jaguar Software Version 3.49.0
Main Software Version 4.446.0
 Time/Date **10:11 19/12/2016**

9 MODULES WITH FAULTS
8 MODULES WITH NO FAULTS
6 MODULES NOT FITTED OR NOT COMMUNICATING

MODULES WITH FAULTS

ENGINE CONTROL MODULE

7 Fault(s) Present

PERMANENT P0102 MASS OR VOLUME AIR FLOW CIRCUIT LOW INPUT.
PERMANENT P0405 EXHAUST GAS RECIRCULATION VALVE DRIVE CIRCUITS - LOW VOLTAGE.
PERMANENT P0445 EVAPORATIVE EMISSION CONTROL SYSTEM VALVE CIRCUIT SHORTED
PERMANENT P0447 EVAPORATIVE EMISSION CONTROL SYSTEM VENT CONTROL CIRCUIT OPEN.
PERMANENT P1260 SECURITY INPUT
PERMANENT P1410 AIR CLEANER INLET CONTROL CIRCUIT
PENDING P1000 SYSTEM CHECK NOT COMPLETED SINCE LAST MEMORY CLEAR

FRONT ELECTRONICS CONTROL MODULE

1 Fault(s) Present

B1503 - Lamp turn signal right - circuit failure

CLIMATE CONTROL MODULE

10 Fault(s) Present

B1265 - Cool air servo motor circuit failure
B2796 - Driver solar radiation sensor circuit open
B2426 - Passenger's solar radiation sensor - circuit open
B1264 - Foot servo motor circuit failure
B1242 - Recirculating air flow door actuator - circuit failure
U2521 - Missing message from the ABS
U2720 - Missing message from instrument cluster
B1676 - Battery voltage out of range
B1263 - Vent servo motor - circuit failure
B1262 - Defrost servo motor - circuit failure