

Z SERVICE

S-TYPE	Date 01/2000	S960-01
TECHNICAL BULLETIN		

Subject REVISED REPAIR OPERATIONS AIR CONDITIONING COMPRESSOR	Model S-TYPE Year 1995.25 ON VIN L00600 ON
---	--

ISSUE:

Air Conditioning System Compressors for S-TYPE vehicles are supplied via Jaguar Parts Operations without the Drive Clutch Field Coil. This necessitates revisions to the Repair Operation Times covering repairs that involve replacement of the Air Conditioning Compressor or of the Compressor Drive Clutch Field Coil.

ACTION:

Please amend your Repair Operation Time Schedule to reflect the following amendments and additional entry.

APPLICABLE TO ALL S-TYPE VEHICLES ONLY

SRO	OPERATION	LABOR TIME ALLOWANCE	
		3.0 L	4.0 L
82-10-08	Compressor Drive Clutch - Renew -	Delete Entry	Delete Entry
82-10-20*	Compressor - Renew -	0.65 hours	0.70 hours
82-10-25**	Clutch Field Coil - Renew -	0.65 hours	0.70 hours

* Amended Entry
 ** Additional Entry