



Sales Order Acknowledgement

Order No 96032

Page: 1
Date: 12/12/19

Harrop Engineering Australia Pty. Ltd.
95 Bell Street Preston VIC 3072 Australia
Phone: +613 9474 0900
Fax: +613 9474 0999
Email: accounts@harrop.com.au
ABN: 87 134 196 080

Sold To: John VIC Australia	Ship To: John VIC Australia
--	--

Customer Id YANJHN	Terms COD	Ship Via Customer Collect	Phone
Your PO Number COUNTER JY 10/12	Ship To Email	INCO Term	INCO Destination

Item	Part Number	Description	Ship Date	Unit	Price/Unit	Qty	Total
0001	60-SC-REPAIR	Repair/Rework Supplied Supercharger 112 Supercharger kit for oil change and cleaning of parts - Supercharger has done approx. 100,000k's Please also inspect for any damage Unit from Jag 4.2L engine Technician's report - Oil replaced with NYE605 S/C oil 190ml - Parts cleaned as requested - 3 Hours labour required - Supercharger spun on test bench - no issues found - Rotor group and bearings not removed from housing (no replacement parts available) - Engine oil found inside supercharger - cleaned where possible - Front cover re-assembled, gasket and bolts re-used (Harrop unable to source new bolts or rubber bushes) - Throttle body not fitted as no bolts available	17/12/19	EACH	220.00	1.000	220.00

If you have any questions, please call : 03 9474 0900

SubTotal	\$220.00
Taxes	\$22.00
Freight	\$0.00
Total	\$242.00

Please remit funds to:

Bank Name: Bank SA
Account Name: Harrop Engineering Australia Pty Ltd
BSB: 105-900
Account Number: 970 876 040

* Prices are stated in Australian Dollars

Please reference your S.O. number : 96032