



X-TYPE

DATE 08/05

XT303-22

SERVICE

# TECHNICAL BULLETIN

Cooling Fan Module –  
Remove/Install –  
Revised Procedure & SRO Time

MODEL 2002 MY-ON  
X-TYPE  
VIN C00001-ON

**Issue:**

This Technical Bulletin has been issued for information only, to inform dealers of a change in the workshop procedure to remove/install the cooling fan module. The air cleaner intake tube no longer needs to be removed during the procedure.

**Action:**

Should it become necessary to remove a cooling fan module on an X-TYPE, please refer to Global Technical Reference (GTR) X-TYPE Workshop Manual Section 303-03A, Cooling Fan Module.

**Global Technical Reference (GTR) Workshop Manual Information:**

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

**Warranty Information:**

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

**Note:** Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

**Note:** Superseded repair time - Cooling fan module 26.25.38 0.90 hours.

Description	SRO	Time	Causal Part Number
Cooling fan module - remove and install	26.25.38	0.80 hrs.	-

**NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.**

