

XF 12 MY Correct Location of Front Number Plate / Plinth

Issue: Incorrect location of the front number plate and/or the plinth.

Cause: For ACC - If the front number plate / plinth is not located / aligned correctly on the front bumper cover, this can generate customer concerns of incorrect operation of the ACC system by blocking the radar signal.

For non Adaptive Cruise Control (ACC) - If the front number plate is not located / aligned correctly on the front bumper cover, this can generate customer concerns of poor visual appearance / reflection of the number plate in the upper grille chrome surround trim.

Action: For ACC and non ACC - please refer to the PDI manual and the PDF doc attached to this document for correct location and fitting instructions.

☒ Pictures 1-3-5 and 7 show NA and SC non ACC variant.

☒ Pictures 2-4-6 and 8 show NA and SC ACC variant.

Note: European market vehicles with ACC will be supplied with the number plate plinth already fitted by Jaguar.

Non ACC



ACC







