

Vehicle Diagnostic Report

The Report is created by **LAUNCH X431**

Repair Shop

Shop Name:Galaxy Tyres & Oil
 Address:M32/1 Mussafah AUH Abu Dhabi Abu Dhabi
 Zip Code:93312
 Telephone:0563290504
 Email:info@galaxytyreshop.com
 SN:987591833100
 Test Time:2020-08-24 06:40:16



Vehicle Information

Year:2011
 Make:JAGUAR
 Model:XF(X250)
 VIN:SAJAA05D6BFS04333
 Odometer:172238 km
 Vehicle Software Version:V33.78
 Diagnostic Application Version:V5.02.027
 Diagnostic path: > Health Report



Inspection Result

ICM (Infotainment Control Module) 1 problems exist

1.U0197-00 Lost communication with the telephone control module Permanent

FACP (Integrated Control Panel) 2 problems exist

1.U0140-00 Lost communication with body control module Intermittent
2.U0156-00 Lost communication with information center A Intermittent

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.SRS (Supplemental Inflatable Restraint System)
- 5.IPC (Instrument Cluster Control Module)
- 6.GSM (Gear Shift Module)
- 7.HCM (Headlamp Control Module)
- 8.ICS (Impact Classification System)
- 9.PBM (Parking Brake Control Module)
- 10.DDM (Driver's Door Module)
- 11.BCM (Body Control Module)
- 12.HVAC (Heating Ventilation And Air Conditioning Control Module)
- 13.RFA (Keyless Vehicle Module)

14.PAM (Parking Assist Control Module)

15.PDM (Passenger's Door Module)

16.BCMB (Auxiliary Junction Box (body Control Module B))