


Unrelated Events (Distance)


events.session.vin: SAJAA061797R45681
 events.session.created: Fri 25-Jan-2013 16:02
 events.session.printed: Fri 25-Jan-2013 16:05



DTC	ECU	Distance	Description	Status	Options	Relevance
Events at 41,431mi						
U0155-00	SCME	41,432mi	Lost communication with instrument cluster control module			0%
Events at 41,418mi						
B1261-23	BCMB	41,419mi	Fuel filler door release switch			0%
Events at 41,156mi						
U3003-62	ABS	41,157mi	Battery voltage			0%
Events at 41,086mi						
U3003-16	HCM	41,086mi	Battery voltage			0%
Events at 40,756mi						
U0231-87	BCM	40,757mi	Lost communication with the rain sensing module			0%
Unknown Events						
P176A-13	GSM	-----mi	Transmission range selector up and down position circuit			0%
P0405-21	PCM	-----mi	Exhaust gas recirculation sensor A - circuit low			0%
U0404-68	TCM	-----mi	Invalid data received from gearshift control module			0%


Untested DTCs: Show Hide On demand self-test DTCs: Show Hide

Tools



Related Events (Distance) [Summary](#) [Event View](#)

events.session.vin: SAJAA061797R45681
 events.session.created: Fri 25-Jan-2013 16:02
 events.session.printed: Fri 25-Jan-2013 16:05



DTC	ECU	Distance	Description	Status	Options	Relevance
Events at 42,090mi						
U0401-68	ABS	42,090mi	Invalid data received from engine control module/powertrain control module			3%
U0401-92	GSM	42,090mi	Invalid data received from engine control module/powertrain control module			0%
U0415-92	GSM	42,090mi	Invalid data received from ABS control module			0%
Unknown Events						
U101B-87	TCM	-----mi	Lost communication with GSM - multiple bus			99%

Untested DTCs: Show Hide On demand self-test DTCs: Show Hide

- Tools
- [CAN Link Monitor](#)
- [Clear VCM](#)
- [DMM](#)

m-harr94 - XF (X250) R45681 - 25 Jan 2013 16:05 (DVD132.04 v.124) The VCM is connected.