Service Needs - Estimated Investment

Joe Simoules - Rosenthal Jaguar 703-893-5703

Repair Order Number: 375784	Advisor:		
Customer Name: THOMAS SENECA	Mileage: 78,940		
Needs Related to Original Concern	Labor	Parts	Total
DIAGNOSTIC TIME FOR RESTRICTED PERFORMANCE — Done	\$137.00		\$148.00
REPLACE FAULTY THROTTLE BODY ASSY	\$205.50	\$510.00	\$779.25
R&R INTAKE TO REPLACE LEAKING VACUUM HOSE	\$822.00	\$56.00	\$885.00
VA INSPECTION			\$16.00
	\$1,164.50	\$566.00	\$1,828.25
Immediate Needs	Labor	Parts	Total
FRONT CONTROL ARM BUSHINGS LEAKING	¢414 00	¢4 252 00	¢1 022 42
FRONT CONTROL ARM BUSHINGS LEAKING REAR TOE LINK BOOTS SPLIT	\$411.00 \$274.00	\$1,353.00 \$459.00	\$1,933.13 \$790.38
4 WHEEL ALIGNMENT	\$169.95	Φ459.00	\$169.95
+ WHILLE ALIGNIVIENT	φ109.93		\$109.95
REAR BRAKES LOW	\$342.50	\$506.00	\$911.75
LESS \$100.00 ONLINE COUPON			-\$100.00
Immediate Needs Total	\$1,197.45	\$2,318.00	\$3,705.20
Related and Immediate Needs Total	\$2,361.95	\$2,884.00	\$5,533.45
Maintenance Needs	Labor	Parts	Total
ALL PRICES INCLUDE TAX AND SHOP SUPPLIES			
Itens marked "* Required			
to pass inspection			
TOTAL MAINT NEEDS			
Total Investment	\$2,361.95	\$2,884.00	\$5,533.45
Approved By:			
Date/Time:			

MSX International H29589.xls

Date Originated: 06/09/2005 Date Revised: 06/09/2005