


Connector: **C44-L**

CONNECTOR HOUSING NOT SERVICEABLE

Description: **Rear bumper harness to telematics harness**

Location: **Adjacent to spare wheel - LH side**

Qualifier:




BLACK

Part No.: **YPC902310**

Colour: **BLACK**

Cavities: **4WY**

Harness: **REAR BUMPER HARNESS**



Wire Chart and Service Repair Kit Information

CAV	CSA	COL	CCT	DESTN	Pre-Terminated Lead	Extract Tool	Crimpers	Wire Stripper	Heat Shrink Sleeve	Ident Sleeve	Splice
1	0.5	GN	J3KAB	C4MP19	418-411-45	-	418-116A	418-117	-	418-112	418-107
2	0.5	GN	J3KAB	C4MP19	418-411-45	-	418-116A	418-117	-	418-112	418-107
3	0.5	YE	J3KAB	S/JOINT SPL266	418-411-45	-	418-116A	418-117	-	418-112	418-107
4	0.75	GN	J3KAB	C4MP19	418-411-45	-	418-116A	418-117	-	418-112	418-107