

Sgt
28/2012

[IDS-DVD119_V8.00] XJ range 06 / 100-00 Complete vehicle

100-00 Complete vehicle

- ABS control module [00 DTC]
- Restraints control module [00 DTC]
- Air suspension module [00 DTC]
- Climate control module. [00 DTC]
- Cellular telephone control module [ERR 0x24]
- Driver's door module [01 DTC]
- Audio unit. [00 DTC]
- General electronics control module. [01 DTC]
- Instrument pack [02 DTC]
- Navigation control module [00 DTC]
- Parking aid control module [00 DTC]
- Parking brake control module [00 DTC]
- Powertrain control module [10 DTC]
 - P0351-00
 - P0352-00
 - P0354-00*
 - P0366-00
 - P1368-00
 - P0171-00
 - P0174-00
 - P0086-00
 - P0087-00
 - U0426-00
 - Not tested [272 DTC]
 - Rear electronic control module. [07 DTC]
 - Steering column lock module [00 DTC]

P0171-00

Description:
System too lean (bank 1)
General failure information - no sub type information.

System malfunction indicator lamp:
System malfunction indicator lamp (if fitted) is activated.

Freeze frame data

Freeze frame[0]

	SUPP	
FCFF	P0171	
FSS #1	0x2	
FSS #2		
CLV	67.06	%
ECT	96.00	°C
STFTB1	-5.47	%
LTFTB1	20.31	%
STFTB2	7.03	%
LTFTB2	20.31	%
FPR	366.00	kPa
IMAP	38.00	kPa
RPM	2085.00	r/min
VS	113.00	km/h
IAT	38.00	°C
MAF	36.63	g/sec
ATP	29.41	%
TPA		%
TAES		s
GPA		
FRT		°C
ERC		

V