

IDS

[IDS-DVD118_V6] P7 XJ Series 01-02 / 100-00 Complete vehicle

100-00 Complete vehicle

- Anti-lock braking system [00 DTC]
- Restraints control module [00 DTC]
- Climate control module. [00 DTC]
- Engine control module [02 DTC]
 - P1000
 - P1384**
- Instrument pack [00 DTC]

Other

- Transmission control module [01 DTC]

P1384

Description:

Variable camshaft timing solenoid 1 malfunction

Variable camshaft timing solenoid 1 malfunction The actuator provide up to 30 degrees of relative crankshaft rotation. The on-board diagnostic compares the target with the actual position of the cam over a 10 second period. The target error is >20 degrees.

start

IDS

[IDS-DVD118_V6] P7 XJ Series 01-02 / 100-00 Complete vehicle

100-00 Complete vehicle

- Anti-lock braking system [00 DTC]
- Restraints control module [00 DTC]
- Climate control module. [00 DTC]
- Engine control module [02 DTC]
 - P1000**
 - P1384
- Instrument pack [00 DTC]

Other

- Transmission control module [01 DTC]

P1000

Description:

System check not completed since last memory clear

System check not completed since last memory clear The diagnostic trouble code indicates that the service drive cycle was not completed satisfactorily. The logging of this code implies that the on-board diagnostics require more time to form a proper judgement of the vehicle faults.