

Service History 2001 Jaguar XJ8  
Purchased 11/4/2003 \$26250 (New Car placed in Service 8/30/2001)  
Grand Total We have paid for Repairs/Maintenance Todate

16984.46

Date	Mileage	Description of Work	Cost	Total
5/4/2011	98333	Front Wheel Bearing on Passenger side -International Auto (Peter) Wallingford CT Labor - 2.4 hours @ \$80/hour plus Sales tax & shop supplies	205.64	
		4/29/11 Front Wheel Bearing - Ebay (amproparts) \$19.95 less \$2 Ebay discount	17.95	223.59
4/28/2011		Costco - GoodYear Assurance Wiper Blade \$7.99		8.47
4/27/2011	98155	Scott's Labor - 2 hrs to install Thermostat Housing & Thermostat (R&I Intake)	120.00	
4/22/2011		Rock Auto Parts - Radiator Hoses (Upper \$7, Lower \$28). Bypass Hose \$2 discount code \$2 express shipping \$21	55.85	
4/10/2011		Welsh Enterprises - Thermostat part# AJ8-6484 \$24.95 plus shipping \$7.85 Bbautoparts.com on loffer.com - ALUMINUM Thermostat Housing Kit \$30 +ship Advance Auto Parts - 1 gal - Prestone Dex Cool Coolant \$13.99 less \$2.80 discount	32.80 38.50 11.86	247.15
3/24/2011	96990	Town Fair Tire - 4 new Kumho Platinum Ecsta LX all season tires \$370.44 +tax Mount on our extra rims, balance and install on car, part of this package is Free flat repair and rotation, Free Snow tire changeover - pkg cost \$95.80 +tax	392.66 101.55	
3/23/2011		4/25/11 \$70 refund check from Town Fair Tires (matches Tirerack deal) Tom's Foreign Auto Parts - 4) XJ8 used rims \$180 plus tax	-70.00 190.80	698.17
3/24/2011	96987	100,000 miles mant - International Auto (Peter) in Wallingford CT Labor \$80/hr (Drive belt \$32 Coolant \$32 Brake Fluid \$64 Engine Oil & Oil Filter \$32 Air Cleaner Filter \$?? Spark Plugs \$144 plus tax Power Steering Fluid Change - No Charge Parts: Accessory Drive Belt - (R&R Auto World - Meriden CT) Gates K070922 \$40 Coolant (antifreeze) -Advanced Auto Parts - 3 gals \$26.71 Preston Dex-Cool Brake Fluid Dot 4- Jaguar Parts - Woodbridge CT - 1 Quart \$18.28 BG brand Engine Oil - Walmart - 2) 5 Quart Jugs \$49 (10 qts) Mobil 1 0w-30 Engine Oil Filter - Advanced Auto Parts - \$6 Bosch Premium 72209 Air Cleaner Filter - Jaguar Parts - Woodbridge CT - Jaguar branded \$45 Spark Plugs - Advanced Auto Parts - 8 totaled of \$36 NGK Iridum BXR6EIX-11 Power Steering Fluid -Advanced Auto Parts - 2 qts \$12 used - AT fluid Mobil 1 Dextron/Metrcon AT Total Parts plus 6% sales tax	322.24 247.00	569.24
12/2/2010	94004	tirerack.com - 4 new Michelin X-Ice Xi2 Ice and snow tires Promotion - Tirerack/Michelin prepaid credit card of \$70 for buying 4 tires Wallingford Tire - winter tire change over	524.12 -70.00 95.53	549.65
9/14/2010	91826	Eriksson Industries - <b>rebuild our existing transmission</b> (replace freewheel, valve body main pressure regulator, valve body other plate, spag, forward drum, rebuild existing torque converter, fill transmission with fluid and dyno test the transmission) Scott's Labor to remove and install transmission Langan Volkswagen - 3) 1 liter transmission fluid bottles	2432.70 550.00 60.42	3043.12
7/17/2010	90758	Jaguar dealer parts dept- Oil & Filter & coolant + hose Scott <b>Labor-Replace cam chains &amp; tensioners + water pump</b> + Oil & Filter	125.00 750.00	
7/14/2010		Fedex Returned Tools	40.28	
7/13/2010		Christopher's Napa NJ - Refunded Deposit on Tools	-424.00	
6/29/2010		Christopher's Napa NJ - <b>Cam chains &amp; tensioners kit + water pump + Tools</b> water pump \$74.95, rental of tools \$75, timing chain kit \$649, deposit \$424	1222.95	
6/26/2010		Jaguar of Hartford - Troubleshooting Engine problem	139.67	
6/23/2010		Scott inspected Engine trouble - Restricted Performance	100.00	1953.90

4/9/2010		Advance auto parts - fuse assortment - for car lighter	15.89	15.89
12/17/2009		Scott Installed new rotors and pads on front and rear	100.00	
12/6/2009		Auto Parts Warehouse - <b>Front &amp; Rear rotors and pads</b> Rotors (Front \$122.95) (Rear \$157.90) Pads (Front \$84.95) (Rear \$97.95) disc \$25	438.75	<b>538.75</b>
12/4/2009	86931	Hartford Jaguar - 6 month service - Oil change with oil filter Oil \$43.15, oil filter \$17.95, Labor \$28.00 Pressure checked water pump and added coolant 15% discount on Labor & Parts plus Jag discount on Labor Enviornmental & shop charge \$5.00 - 6% sales tax on total also replaced wiper blade (warranteed - no charge) <b>Need rotors &amp; pads for front &amp; rear- Est for rear \$705.00</b>	71.15 61.00 -30.67 11.39	112.87
11/5/2009	85800	Walmart - New battery - maxx-49n \$80.00 plus tax Jim install the battery	84.80	84.80
6/4/2009	78709	Darien Jaguar - Oil Change (Motorcraft) with Oil filter \$60.95 Replace wiper inserts \$22.70 Brake Flush service \$113.50 + 4.00 (shop supples)	54.92 20.45 106.50	181.87
11/21/2008	73273	Jaguar Southington -Oil Change with Oil filter \$31.95; Labor \$39.50 Also adjusted emergency brakes \$15.00	75.74 15.90	91.64
5/2/2008	67676	Jaguar Southington - 70M mile service(Labor \$128) Oil Change with Oil filter \$31.95; Rubber windshield wiper \$22.66		193.57
4/23/2008	67445	Jaguar Southington - Replace Fuel Pump & Lead-Link Mercury Warantee Paid for Replacement and Fuel Pump cost of \$185 plus Labor of \$350 - a total \$535 We paid for the Lead-Link wire	135.84	135.84
12/5/2007	64537	Jaguar Southington -Oil Change with Oil filter \$31.95; Oil Change with Oil filter \$31.95; Rubber windshield wiper \$22.66 plus Labor \$19 Tax on CD Player Jaguar Southington - refunded the tax Replace 10 disks CD Player -Mercury Insurance Extended Warrantee Claim (\$160 for CD player after exchange & \$95 labor - total was \$255)	75.74 44.16 15.30	135.20 -15.30
11/13/2007		Cheshire Gulf Service Station - Detailing		189.00
5/16/2007	57923	Jaguar Southington - 60M mile service (Labor \$208.50) Oil Change with Oil filter \$61.95 (Labor \$30 - .5 hrs) Air Filter element \$60.07 (Labor \$17 -.2 hrs) Pump out Brake Fuild & replace it \$101.12 (Labor \$85 - 1.0 hrs) Replace Fuel Filter \$76.82 (Labor \$42.50 - .5 hrs) Throttlebody service \$25.50 all Labor - .3 hrs Lubricate door hinges & sun roof tracks n/c Clear fuel door drain n/c Clean part load breather \$8.50 all labor	347.87	347.87
5/15/2007	57888	Costco - Snow tires removed/Reg Tires installed	25.44	25.44
10/17/2006	53426	Costco - Purchased 4) Michelin X-ice snow tires	449.40	449.90
10/10/2006		Jagbits - New Front Signal Light assembly		

		& Rear Tail Light assembly	337.11	337.11
9/5/2006		Towne Fair Tire -Flat repair	14.73	14.73
9/1/2006		Cliff Jacobs Wheel Repair Repair bent rim	100.00	100.00
8/31/2006		Fedex ship Rim to Cliff Jacobs	13.93	13.93
8/30/2006		Knucklebusters Used Auto Parts Replacement Fog Lamp (Len was broken) Wrong Part - Returned 10/10/2006	95.00	95.00 -80.00
8/24/2006		Cliff Jacobs Wheel Repair weld in patch on spare tire rim	85.00	85.00
7/19/2006	50587	Stephen Jaguar - Oil Change with Oil Filter & replace rubber wiper blade & Balance/rotate tires	187.91	187.91
5/2/2006	48000	Town Fair Tires - Snow Tires Changeover package - includes wheel alignment	94.34	94.34
1/17/2006	45205	Stephen Jaguar - 28 Isolators for valve covers	83.11	83.11
1/17/2006	45205	Stephen Jaguar - Schedule 8:00am Replace Valve Cover Gaskets -Extended Warrantee Claim (\$449.35)	0.00	0.00
1/12/2006	45130	Stephen Jaguar - Lub & Oil change Note: Valve Cover Gaskets are leaking Also Burning Smell when heater is on Service could not duplicate this condition	75.74 0.00	75.74
11/3/2005	43000	Town Fair Tires - Snow Tires Changeover	42.40	42.40
11/3/2005	43000	Anderson Tire - Emission Test & Tire Repair	33.78	33.78
8/15/2005	40249	Stephen Jaguar - Replaced Water Pump	0.00	0.00
7/27/2005	39670	Stephen Jaguar - Labor - Replace Front Brake pads & rotors	147.87	
7/22/2005		Tire Rack - Front Brake pads (\$62) & Brembo Rotors (\$61 x 2) plus shipping \$24.02	208.02	355.89
7/25/2005		Bayer Federal Credit Union - Purchased Extented Service Warrantee - Warrantee company is Mercury Insurance Co (Mercury Select Management Co) Premium Valve GOLD Coverage	2250.00	2250.00
7/20/2005	39531	Thomas Jaguar - Lub & Oil change 40000 mile service Replaced Fuel Cap Replaced J-Gate Module (Shifter Housing Gasket) Replaced Left Front door rubberseal Sunroof - Repair Link Assy & Reinstall Note: Found Front Pads & Rotors need replacement -Est \$736 Front Control Arms Bushings cracked Replaced front bushings & Align Front Replace Rear Pinion Seal	0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00	
3/22/2005	34802	Thomas Jaguar - Winter Lub & Inspection service Lub & Oil change with 24 point inspect	136.44	

		Replaced Left Front Door rubber seal	0.00	
		Replaced SOP Sensor - Outside Temp	0.00	
		Replaced Coolant Level Sensor	0.00	136.44
11/16/2004	31306	Thomas Jaguar - Replaced both Front doors rubberseals	0.00	
7/20/2004	27948	Thomas Jaguar - Lub & Oil change 30000 mile service	0.00	
		Replaced outside air temp sensor	0.00	0.00
7/15/2004	27500	Town Fair Tire - Snow Tire Changeover to regular tires	59.65	
		Repaired Flat Tire	3.95	63.60
4/2/2004	24432	Thomas Jaguar - Lub & Oil change with 24 point inspect	89.38	
		sunroof -refit & align lift arms clean & lub		
		roof tracks repair spring clips	0.00	89.38
1/8/2004	22200	Thomas Jaguar - Replaced Windshield Wiper Arm	38.69	38.69
12/12/2003	21900	Bargain News - Purchased 4 used Pirelli Snow Tires	100.00	
		Town Fair Tires - Put on Snow Tires	42.19	142.19
12/10/2003		Est Date - Replace Front Windshield	0.00	0.00
		Insurance Claim paid for it		
12/2/2003	21857	Thomas Jaguar - Lub & Oil change	57.80	
		Replaced Windshield washer hose	0.00	57.80
11/14/2003	20600	Town Fair Tire - 4 Pirelli p6000 Tires	596.00	
		" - 4 wheel Alignment	44.00	640.00
11/10/2003		Sales Tax	1596.00	
		Auction Fees	350.00	
		Auction Commission	200.00	2146.00
11/5/2003		RodeWay Inn - lodging Auction		33.30
11/3/2003		CarFax		24.99
11/1/2003		Train Tickets to Auction		142.50