

Jaguar XJ Major Repair & Safety Issues  
Information gathered from relevant forum posts and other internet websites

Jaguar XJ8 & XJR model Series

Major Repairs & Safety Issues at a Glance

Engine Issues

XJ8 and XJR Models

| Issues Description                         | Model Years/Vin Range Effected                    | Buttons to Summary Information   |
|--|---|----------------------------------|
| Engine - Secondary Timing Chain Tensioners | 1998-2002 MY V8 XJ Series Vin Range 812256-F41862 | <a href="#">XJ Tensioners</a>    |
| Engine - Throttle Body                     | 1998-2002 MY V8 XJ Series Vin Range 812256-F41862 | <a href="#">XJ Throttle Body</a> |

Transmission Issues ZF 5hp24

XJ8 Models

|  |  |                                  |
|--|--|----------------------------------|
| Transmission - Fractured "Forward Drum"          | 1998-2002 MY V8 XJ8 Series Vin Range 812256-F41862 | <a href="#">XJ8 Forward Drum</a> |
| Transmission - Valve Body                        | 1998-2002 MY V8 XJ8 Series Vin Range 812256-F41862 | <a href="#">XJ8 Valve Body</a>   |
| Transmission - TCM (Transmission Control Module) | 1998-2002 MY V8 XJ8 Series Vin Range 812256-F41862 | <a href="#">XJ8 TCM</a>          |

Transmission Issues W5A580

XJR Models

|   |                            |                         |
|---|----------------------------|-------------------------|
| Transmission - TCM (Transmission Control Module)" | 1998-2002 MY V8 XJR Series | <a href="#">XJR TCM</a> |
|---|----------------------------|-------------------------|

Jaguar XJ Major Repair & Safety Issues  
Information gathered from relevant forum posts and other internet websites

Jaguar XJ8 & XJR model Series

Major Repairs & Safety Issues - Requested Information

Issues Description

Model Years/Vin Range Effected

Engine Issues

XJ8 and XJR Models

Engine- Secondary Tensioners

1998-2002 MY V8 XJ Series Vin Range 812256-F41862

Reference information on Issue

|                           |  |
|---------------------------|--|
| Safety Issue              | Car goes into Restricted Performance called Limp Mode - One owner said "car has stalled at highway speeds and I was in fear of a major accident"   |
| Repair Costs Range        | Low Range - \$600 for both top Secondary Tensioners High Range - \$10000 or more for new engine  |
| Brief Summary Statement   | Excerpt from Jags-lovers.org on this issue: "The weak link is the upper chain tensioners"; "plastic used breaks down after a period of time"; "One tooth skipped and engine will run roughly, two teeth and engine will self-destruct, with valves and pistons coming together." |
| Trouble Message Displayed | "Restricted Performance"   |

Menus to Reveal Forum Posts and Related Information

Move Mouse Pointer to Menus and Click on a Menu Option

[Relevant Forum Posts](#)

[DIY Posts & Articles](#)

[Comments on the Issue](#)

[TSB Bulletins / JTIS](#)

[Click on button to return](#)

Summary at a Glance

Jaguar XJ Major Repair & Safety Issues  
Information gathered from relevant forum posts and other internet websites

Jaguar XJ8 & XJR model Series

Major Repairs & Safety Issues - Requested Information

Issues Description

Model Years/Vin Range Effected

Engine Issues

XJ8 and XJR Models

Engine - Throttle Body

1998-2002 MY V8 XJ Series Vin Range 812256-F41862

Reference information on Issue

Safety Issue

Car goes into Limp Mode

Repair Costs Range

Low Range - \$???? High Range - \$????

Brief Summary Statement

Excerpt from Poster on townhall-talk.edmunds.com forum. I have a '99 XJ8 and the throttle stuck as I tried to break at the first traffic light Didn't want to stop but after hitting the brakes hard and steady, it slowed, shuddered, stopped and stalled. If I hadn't reacted quickly enough, I would probably have plowed into a vehicle at the light.

Trouble Message Displayed

"Restricted Performance"

Menus to Reveal Forum Posts and Related Information

Move Mouse Pointer to Menus and Click on a Menu Option

[Relevant Forum Posts](#)

[DIY Posts & Articles](#)

[Comments on the Issue](#)

[TSB Bulletins / JTIS](#)

[Click on button to return](#)

Summary at a Glance

Jaguar XJ Major Repair & Safety Issues  
Information gathered from relevant forum posts and other internet websites

Jaguar XJ8 & XJR model Series

Major Repairs & Safety Issues - Requested Information

Issues Description

Model Years/Vin Range Effected

Transmission Issues ZF 5hp24

XJ8 Models

Transmission - Fractured "Forward Drum

1998-2002 MY V8 XJ8 Series Vin Range 812256-F41862

Reference information on Issue

Safety Issue

Car goes into Limp Mode

Repair Costs Range

Low Range - \$600 for Forward Disk with R&I High Range -\$3000 to \$6000 for a rebuild or rebuilt Transmission

Brief Summary Statement

The Forward Clutch Drum is a known problem with this transmission .It is located near the torque convertor. New design forward drum is available and drum has been reinforced. Also may have problem with the valve body located in tranny pan or the TCM (Transmission Control Module).

Trouble Message Displayed

"Gearbox Fault"

Menus to Reveal Forum Posts and Related Information

Move Mouse Pointer to Menus and Click on a Menu Option

[Relevant Forum Posts](#)

[DIY Posts & Articles](#)

[Comments on the Issue](#)

[TSB Bulletins / JTIS](#)

[Click on button to return](#)

Summary at a Glance

Jaguar XJ Major Repair & Safety Issues  
Information gathered from relevant forum posts and other internet websites

Jaguar XJ8 & XJR model Series

Major Repairs & Safety Issues - Requested Information

Issues Description

Model Years/Vin Range Effected

Transmission Issues ZF 5hp24

XJ8 Models

Transmission - Valve Body

1998-2002 MY V8 XJ Series Vin Range 812256-F41862

Reference information on Issue

|                           |   |
|---------------------------|---|
| Safety Issue              | Car goes into Limp Mode   |
| Repair Costs Range        | \$??? for Valve Body replacement High Range -\$3000 to \$6000 for a rebuild or rebuilt Transmission   |
| Brief Summary Statement   | May have a problem with the valve body located in transmission pan. Also the forward drum should be replaced with New design forward drum that has been reinforced. |
| Trouble Message Displayed | "Gearbox Fault"   |

Menus to Reveal Forum Posts and Related Information

Move Mouse Pointer to Menus and Click on a Menu Option

[Relevant Forum Posts](#)

[DIY Posts & Articles](#)

[Comments on the Issue](#)

[TSB Bulletins / JTIS](#)

[Click on button to return](#)

Summary at a Glance

Jaguar XJ Major Repair & Safety Issues  
Information gathered from relevant forum posts and other internet websites

Jaguar XJ8 & XJR model Series

Major Repairs & Safety Issues - Requested Information

Issues Description

Model Years/Vin Range Effected

Transmission Issues ZF 5hp24

XJ8 Models

Transmission - TCM (Transmission Control Module)

1998-2002 MY V8 XJ Series Vin Range 812256-F41862

Reference information on Issue

Safety Issue

Car gets stuck in 2nd Gear

Repair Costs Range

Low Range - \$??? High Range - \$????

Brief Summary Statement

Excerpt from Jaguar Forum - When I'm accelerating from a standstill the car pulls away as normal and seems however if I back off on the throttle before it gets into 3rd gear then it stays in second and the engine gives me braking as if i was holding it in 2nd gear manually.

Trouble Message Displayed

No Message Displayed

Menus to Revelent Forum Posts and Related Information

Move Mouse Pointer to Menus and Click on a Menu Option

[Relevant Forum Posts](#)

[DIY Posts & Articles](#)

[Comments on the Issue](#)

[TSB Bulletins / JTIS](#)

[Click on button to return](#)

Summary at a Glance