

Mark Morgan 16 Aldwych Close Burnham-on-Sea Somerset TA81QD	Estimate 4000645			
	Date	24/03/20	Oper	TR
	Customer Acc Number	MAR005		
	Customer Ord Number			
	Our Reference Number	E 4000119		
	VAT Reg Number	GB 841 0399 39		

PartCode	Description	Unit Price	Disc%	Qty	Price	Value
----------	-------------	------------	-------	-----	-------	-------

To carry out supercharger removal, Remove and replace supercharger front assembly replace supercharger isoslater with Jaguar modified assembly, Refit inlet manifold and supercharger, Replace supercharger belt. Bleed coolant system.

Work Carried Out

L1	Supercharger Labour Charge	65.00		6.00	65.00	390.00
----	----------------------------	-------	--	------	-------	--------

Parts Used

AJ811590	Lower Inlet Gasket	7.01		1.00	7.01	7.01
SCO	Eaton super charger refill kit	25.00		1.00	25.00	25.00
COOLANT	4ltr Anti-Freeze red cold mix	20.00		1.00	20.00	20.00
C2D39175	5.0 Supercharger Belt	38.58		1.00	38.58	38.58
AJ811948	Top supercharger gasket	51.87		1.00	51.87	51.87
AJ811576	Lower Inlet Gasket	6.44		1.00	6.44	6.44
C2D38554	Kit-Supercharger	384.56		1.00	384.56	384.56

Vat	Rate	Goods	Vat
1	20.00%	923.46	184.69

Payment Summary	

Goods & Services	
Goods & Services	923.46
Total Net Amount	923.46
Total VAT Amount	184.69

Vehicle Details	
Registration	M16XKB
Make	Jaguar
Model	XKR-S
Year	01/08/1994
Mileage	52755

Cost Breakdown	
Labour	390.00
Parts	533.46

Total Amount Due	1,108.15
-------------------------	-----------------