

# 315 BG Low Viscosity Full Synthetic ATF

## APPLICATION CHART

BG Low Viscosity Full Synthetic ATF, PN 315, meets or exceeds the performance requirements of the following automatic transmission fluids.

| MAKE                         | ATF PN   |
|------------------------------|--|
| <b>Acura</b>                 | DW-1, TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A   |
| <b>Aisin Warner</b>          | AW-1   |
| <b>Audi</b>                  | G 052 540, G 055 005, G 055 162, G 060 162   |
| <b>BMW</b>                   | 83 22 0 142 516, 83 22 0 144 137, 83 22 2 152 426, 83 22 2 305 396, 83 22 2 305 397, 83 22 2 355 599, 83 22 2 289 720, 83 22 0 397 114, 83 22 2 163 514, 83 22 2 220 445, 83 22 0 024 359, 83 22 0 403 249 |
| <b>Chrysler/Mopar</b>        | 68043742AA, 68043742AB, 68065322AA, 68157995AA, 68157995AB, 68218925AA, 68218925AB, 68171866AA, 68171866AB, 68171869AA, 68171869AB   |
| <b>DSIH</b>                  | 6P805 (GEELY, SSANGYONG, MAHINDRA 6SP)   |
| <b>Ford</b>                  | MERCON®LV (XT-10-QLVC)   |
| <b>GM</b>                    | DEXRON®-VI, 88863400, 88863401   |
| <b>Honda</b>                 | DW-1, TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A   |
| <b>Hyundai/Kia</b>           | SP-IV, SPH-IV, SP-IV-RR, NWS-9638, 040000C90SG, SP4-M  |
| <b>Isuzu</b>                 | SCS 2-90531-200-0  |
| <b>Jaguar</b>                | JDE 26444, C2C8432   |
| <b>JASO</b>                  | 1-A-LV   |
| <b>JWS</b>                   | 3324   |
| <b>Land Rover</b>            | JDE 26444, LR 023288, LR 023289, TYK500050   |
| <b>Lexus</b>                 | WS   |
| <b>Mazda</b>                 | ATF-FZ (0000-FZ-113E-01)   |
| <b>Mercedes-Benz</b>         | 236.12, 236.14, 236.15, 236.16, 236.17, 236.41   |
| <b>Mitsubishi</b>            | ATF-J3, ATF-PA, SP-IV  |
| <b>Nissan</b>                | MATIC-S  |
| <b>Porsche</b>               | 000 043 306 24, 958 300 540 00   |
| <b>Shell</b>                 | M-L12108, 3353, M-1375.4, M-1375.6   |
| <b>Toyota</b>                | WS (JWS 3324)  |
| <b>Volvo</b>                 | 31256774, 31256775   |
| <b>VW</b>                    | G 052 540, G 055 005, G 055 162, G 060 162   |
| <b>ZF Friedrichshafen AG</b> | LifeGuard Fluid 6 (S671090255), LifeGuard Fluid 6 Plus (S671090281), LifeGuard Fluid 8 (AA00601304, S671090312), LifeGuard Fluid 9   |

**BG Low Viscosity Full Synthetic ATF is not recommended for use in the following applications:**

- Ford Type F, Ford MERCON® ULV, XT-12-QULV
- Continuously Variable Transmissions (CVTs)
- Dual Clutch Transmissions (DCT)
- Direct-Shift Gearbox (DSG)
- GM DEXRON®-HP, DEXRON® ULV

**BG Products, Inc., accepts no liability for excessive use or misuse of this product.**

**Revision date** 03-31-20

**Revisions** Added to ZF FRIEDRICHSHAFEN AG section  
- LIFEGUARD FLUID 9

**02-21-20** Added to Ford section  
- (XT-10-QLVC)

**01-28-20** Added to BMW section  
- 83 22 0 144 137, 83 22 2 305 397  
**Added to Chrysler/Mopar section**  
- 68218925AB, 68043742AA, 68043742AB, 68065322AA  
**Added to Not Recommended section**  
- DEXRON<sup>®</sup> ULV

**11-30-18** Added to Porsche section  
- 000 043 306 24, 958 300 540 00

**10-12-18** Added to Acura:  
-DW-1, TYPE 3.0 08200-9016A  
**Added to BMW:**  
-83 22 2 305 396, 83 22 2 355 599, 83 22 2 289 720, 83 22 0 397 114, 83 22 2 163 514,  
83 22 2 220 445, 83 22 0 024 359, 83 22 0 403 249  
**Added to Chrysler/Mopar:**  
-68218925AA, 68171866AA, 68171866AB, 68171869AA, 68171869AB  
**Added to GM:**  
-88863400, 88863401  
**Added to Honda:**  
-TYPE 3.0 08200-9016A, TYPE 3.1 08200-9017A  
**Added to Hyundai/KIA:**  
-040000C90SG, SP4-M  
**Added Isuzu:**  
-SCS 2-90531-200-0  
**Added Jaguar:**  
-C2C8432  
**Added to Land Rover:**  
-LR 023288, LR 023289, TYK500050  
**Added Mazda:**  
-ATF-FZ (0000-FZ-113E-01)

**10-12-18 Added Mercedes-Benz:**

-236.15, 236.16, 236.17

**Changed on Volvo:**

- WAS "31256675" UPDATED TO "31256775"

**Added to Not Recommended section**

- GM DEXRON®-HP

**Removed from Not Recommended section**

- All Mercedes Benz 722.9 transmissions built after June 21, 2010 requiring ATF A0019897803 (236.15)

**9-14-17 Added to Not Recommended section**

- Ford MERCON® ULV, XT-12-QULV

**12-9-16 Fixed on Ford:**

REMOVED SPACE BETWEEN MERCON® AND LV

**10-20-16 Added to Acura:**

-TYPE 3.1 08200-9017A

**11-2-15 Original**