

There are 5 ABS modules for the early X100 (4.0) and the X308 (3.2 and 4.0) sedans.

JLM20129 (X100 1997MY to VIN 018107) Except Traction Control 5 pipes (6 Valve) LJA2210BH

JLM20130 (X100 1997MY to VIN 018107) With Traction Control 6 pipes (9 Valve) LJA2210AH

JLM20555 (X100 from VIN 018108) and (X308) Except Traction Control 5 pipes (6Valve) LNC2210BD

JLM20556 (X100 from VIN 018108 to VIN 042775) and (X308 to VIN 878717) With Traction Control 6 pipes (9 Valve)  
LNC2210AD

JLM21323 (X100 from VIN A00083 to VIN A30644) and (X308 From VIN F00035) With Traction Control 6 pipes (9 Valve)  
LNF2210AD

The JLM20129 and (Especially) JLM20130 are hard to find because of ONE YEAR production.

The numbers printed on the ABS module are NOT the Jaguar numbers listed in the parts catalogue.