2011.75 XJ RANGE (X351), 501-05

INTERIOR TRIM AND ORNAMENTATION

HEADLINER (G1267476)

REMOVAL AND INSTALLATION

REMOVAL



NOTE:

Removal steps in this procedure may contain installation details.

All vehicles

- Refer to: Battery Disconnect and Connect (414-01 Battery, Mounting and Cables, General Procedures).
- Refer to: Interior Rear View Mirror (501-09 Rear View Mirrors, Removal and Installation).
- Refer to: Overhead Console (501-12 Instrument Panel and Console, Removal and Installation).

i. |

\wedge

NOTE:

The procedure must be carried out on both sides.

Refer to: Sun Visor (501-05 Interior Trim and Ornamentation, Removal and Installation).



The procedure must be carried out on both sides.

Refer to: 'A' Pillar Trim Panel (501-05 Interior Trim and Ornamentation, Removal and Installation).

6.

△ NOTE:

The procedure must be carried out on both sides.

Refer to: 'B' Pillar Upper Trim Panel (501-05 Interior Trim and Ornamentation, Removal and Installation).

'.


\triangle NOTE:


The procedure must be carried out on both sides.

Refer to: 'C' Pillar Lower Trim Panel (501-05 Interior Trim and Ornamentation, Removal and Installation).

Refer to: Windshield Glass (501-11 Glass, Frames and Mechanisms, Removal and Installation).


9.






Torque: 2 Nm

11.






13

\wedge

NOTE:

Some variation in the illustrations may occur, but the essential information is always correct.



△ NOTES:

- Make sure that the component is installed to the position noted on removal.
- Right-hand shown, left-hand similar.
- The procedure must be carried out on both sides.




Torque: 2 Nm

15.

\triangle


NOTES:

- Make sure that the component is installed to the position noted on removal.
- Right-hand shown, left-hand similar.
- The procedure must be carried out on both sides.



Torque: 2 Nm

16.




17

⚠ WARNING:

① CAUTIONS:


- Note the fitted position of the component prior to removal.
- Make sure that these components are installed to the noted removal position.



18.

\triangle


NOTE:



19.


\triangle

NOTE:



20

↑ WARNING:



△ NOTES:

- This step requires the aid of another technician.
- Make sure the front and rear passenger assist handles and headliner retaining clips are installed to the headliner prior to installation.




② CAUTION:

Note the fitted position of the component prior to removal.

△ NOTES:

- Make sure that the component is installed to the position noted on removal.
- Right-hand shown, left-hand similar.
- The procedure must be carried out on both sides.




Long wheelbase

.

Δ


NOTES:

- Do not disassemble further if the component is removed for access only.
- Left-hand shown, right-hand similar.





Left-hand shown, right-hand similar.



INSTALLATION

To install, reverse the removal procedure.