



E104721

Note: Tighten bolts in indicated sequence.
Torque to 48Nm