



XJ range

DATE 07/03

XJ204-01

SERVICE

TECHNICAL BULLETIN

**Diagnosing/Servicing Air Suspension –
Gotec Leak Detection Spray –
Specified Hose Cutters**

MODEL 2004 MY-ON
XJ range

VIN G00001-ON

Issue:

This bulletin provides specific recommendations when diagnosing and servicing the hoses of the air suspension on 2004 MY-on XJ range vehicles.

Action:

When carrying out air suspension pipe repairs, follow the workshop procedure outlined in JTIS section 204-05 Vehicle Dynamic Suspension, general procedures, air leaks.

⚠ Caution: When diagnosing leaks in the air suspension, **do not** use soapy water as a means for detecting the source of an air leak. Water can be harmful to the air suspension system, if it enters the air tubing. **Use only** Gotec Leak Detection Spray, part number **C2C 22398**, for this purpose.

If instructed to cut the air pipe, you must use one of the hose cutters outlined below:

- Hose cutter - 204-494 available from SPX OTC.
- Hose cutter - YA 1000A available from Snap-On.