

DTCs by ECU



VIN: SAJWA2GE9DMV43190
Model: Jaguar X351 New XJ
Session creation: Mon 25-Dec-2023 21:54
Session printed: Mon 25-Dec-2023 22:02
Current odometer: 78,386km

DTC	ECU ▼	Distance	Description	Status	Options	Relevance
<input type="checkbox"/> TCM - Transmission control module						
U0416-98	TCM	78,386km	Invalid data received from vehicle dynamics control module			
<input type="checkbox"/> SODL - Side object detection control module - Left						
U0233-00	SODL	78,386km	J_14229_DTC_U0233			
<input type="checkbox"/> SCMF - Rear climate seat module						
U0140-00	SCMF	-----km	Lost communication with body control module			
U0156-00	SCMF	-----km	Lost communication with information center A			
<input type="checkbox"/> SCME - Driver's climate seat module						
U0140-00	SCME	-----km	Lost communication with body control module			
<input type="checkbox"/> RGTM - Rear gate / trunk module						
U0140-00	RGTM	-----km	Lost communication with body control module			
<input type="checkbox"/> RFA - Keyless vehicle module						

U0300-00	RFA	-----km	Internal control module software incompatibility	
B10C5-23	RFA	-----km	Luggage compartment unlock pull switch	

[-] RDCM - Rear differential control module

U0139-00	RDCM	-----km	Lost communication with the suspension control module B	
----------	------	---------	---	--

[-] RCM - Restraints control module

B11A0-87	RCM	-----km	Left side restraints pressure sensor	
B11A1-87	RCM	-----km	Right side restraints pressure sensor	

[-] PSM - Passenger's seat module

U2101-00	PSM	-----km	Control module configuration incompatible	
----------	-----	---------	---	--

[-] PDM - Passenger's door module

B1C15-15	PDM	-----km	Passenger's up/down mirror motor feedback circuit		
----------	-----	---------	---	--	--

[-] PCM - Powertrain control module

U0415-62	PCM	78,386km	Invalid data received from ABS control module			
U0104-00	PCM	78,386km	Lost communication with speed control module			
P0050-00	PCM	78,386km	J_14229_DTC_P0050			100%
U0010-88	PCM	-----km	Medium speed CAN communication bus			
P0497-00	PCM	-----km	J_14229_DTC_P0497			

P0343-00	PCM	-----km	J_14229_DTC_P0343	
P0256-13	PCM	-----km	Injection pump fuel metering control B	
P0073-00	PCM	-----km	Ambient air temperature sensor - circuit high input	
P0480-13	PCM	-----km	Fan 1 control circuit	

[-] IPC - Instrument cluster control module.

U0104-00	IPC	78,386km	Lost communication with speed control module		
B12FE-13	IPC	-----km	Fan		
U0208-00	IPC	-----km	Lost communication with the seat control module A		
U3000-87	IPC	-----km	Control module		

[-] HVAC - Heating ventilation and air conditioning control module



U3002-81	HVAC	78,386km	Vehicle identification number		
B1B62-11	HVAC	78,386km	Pollution sensor nitrous oxide (NOX) input circuit		
B13C2-87	HVAC	78,386km	Windshield misting sensor		
U3000-87	HVAC	-----km	Control module		
B1364-00	HVAC	-----km	Rear left - Temperature damper motor		
U0140-87	HVAC	-----km	Lost communication with body control module		



[-] HCMB - Headlamp control module B



U0140-00	HCMB	-----km	Lost communication with body control module		
----------	------	---------	---	--	--



[-] HCM - Headlamp control module


U2101-00	HCM	78,386km	Control module		
----------	-----	----------	----------------	--	--



			configuration incompatible	 
--	--	--	----------------------------	--







[-] GWM - Gateway module				
B1412-96	GWM	78,386km	Quiescent relay box	 

[-] GSM - Gear shift module				
P0814-01	GSM	-----km	Transmission range display circuit malfunction	
U043A-92	GSM	-----km	Invalid data received from the suspension control module B	



















[-] FCDIM - Front control/display interface module (high level display front)				
U0300-00	FCDIM	-----km	Internal control module software incompatibility	
B1D21-13	FCDIM	-----km	Remote control switch	

[-] DSM - Driver's seat module				
U2101-00	DSM	-----km	Control module configuration incompatible	

[-] DDM - Driver's door module				
B1C14-15	DDM	-----km	Driver's left/right mirror motor feedback circuit	 

[-] CHCM - Chassis control module				
U2101-00	CHCM	78,386km	Control module configuration incompatible	  
P1905-00	CHCM	78,386km	J_14229_DTC_P1905	  


[-] BCM - Body control module

B130E-15	BCM	-----km	Rear left fog lamp		
B130B-15	BCM	-----km	Rear right fog lamp		
B1277-15	BCM	-----km	Reverse lamp		
B109B-13	BCM	-----km	License plate lamp		
B10AD-87	BCM	-----km	Rain sensor		
B113E-23	BCM	-----km	External luggage compartment release switch		
B123A-15	BCM	-----km	Front left turn signal		
B123B-15	BCM	-----km	Front right turn signal		
B1247-15	BCM	-----km	Rear left turn signal		
B1248-15	BCM	-----km	Rear right turn signal		
B1D02-15	BCM	-----km	Left high beam circuit		
B1D03-15	BCM	-----km	Right high beam circuit		
C111A-15	BCM	-----km	Right stoplamp		
C111B-15	BCM	-----km	Left stoplamp		

[-] ACM - Audio front control module

B1D55-13	ACM	-----km	Antenna 2 circuit	
----------	-----	---------	-------------------	---

[-] ABS - ABS control module

U0139-00	ABS	-----km	Lost communication with the suspension control module B	
----------	-----	---------	---	---