

Company:

Address:

Telephone:

# Diagnosis Report

2024-05-08 07:16

## Vehicle Information

Vehicle Name : New-XJ

Year: 2015

Mileage : 115019km

SN: D8-063921

Diagnosis Route : JAGUAR V12.20

## Fault Codes

33 systems detected: 15 systems related to fault codes, 36 fault codes

NO.	System Name	Status
1	<b>Powertrain control module(PCM)</b>	▲ 5
	U0447-00 Invalid data received from gateway A	Intermittent
	P0142-00 Oxygen sensor circuit. Bank 1 - sensor 3	Historic
	P0055-00 Heated oxygen sensor heater resistance (bank 1, sensor 3)	Historic
	P2275-00 Oxygen sensor signal stuck rich. Bank 1 - sensor 3	Historic
	P0497-00 Evaporative emission system low purge flow	Intermittent
2	<b>Rear climate seat module(SCMF)</b>	▲ 4
	U0140-00 Lost communication with body control module.	Intermittent
	U0142-00 Lost communication with body control module B.	Intermittent
	U0155-00 Lost communication with instrument cluster control module.	Intermittent
	U0156-00 Lost communication with information center A	Intermittent
3	<b>Driver's climate seat module(SCME)</b>	▲ 4
	U0140-00 Lost communication with body control module.	Intermittent
	U0142-00 Lost communication with body control module B.	Intermittent
	U0155-00 Lost communication with instrument cluster control module.	Intermittent
	U0156-00 Lost communication with information center A	Intermittent
4	<b>Heating ventilation and air conditioning control module(HVAC)</b>	▲ 4
	B1352-00 Front left - Temperature damper motor	Intermittent
	B1354-00 Rear right - Temperature damper motor	Intermittent
	B1366-00 Front right - Temperature damper motor	Intermittent
	U0010-88 Medium speed CAN communication bus	Intermittent
5	<b>Body control module(BCM)</b>	▲ 3
	C1D21-05 Wheel module	Intermittent
	U0164-00 Lost communication with heating ventilation and air conditioning control module.	Historic
	U0230-00 Lost communication with the rear gate module	Historic
6	<b>Side object detection control module - Right(SODR)</b>	▲ 3
	U0155-00 Lost communication with instrument cluster control module.	Historic
	U0232-00 Lost communication with the left side obstacle detection control module.	Historic
	U0415-68 Invalid data received from ABS control module	Historic
7	<b>Side object detection control module - Left(SODL)</b>	▲ 3
	U0155-00 Lost communication with instrument cluster control module.	Historic
	U0233-00 Lost communication with the right side obstacle detection control module.	Historic
	U0415-68 Invalid data received from ABS control module	Historic

8	Instrument cluster control module.(IPC)		▲ 2
	B12FE-13	Fan	Intermittent
	U0208-00	Lost communication with the seat control module A	Intermittent
9	Driver's seat module(DSM)		▲ 2
	U0011-87	Medium speed CAN communication bus performance.	Intermittent
	U0199-87	Lost communication with the door control module A	Intermittent
10	Gateway module(GWM)		▲ 1
	B13C5-92	Secondary battery	Permanent
11	Speed control module(CCM)		▲ 1
	C1A67-97	Forward looking sensor	Intermittent
12	Rear gate / trunk module(RGTM)		▲ 1
	U0010-88	Medium speed CAN communication bus	Intermittent
13	Passenger's seat module(PSM)		▲ 1
	U0011-87	Medium speed CAN communication bus performance.	Intermittent
14	Front controls interface module 'B' (front audio control panel)(FCIMB)		▲ 1
	U0164-08	Lost communication with heating ventilation and air conditioning control module.	Historic
15	Headlamp control module 'B'(HCMB)		▲ 1
	U0140-00	Lost communication with body control module.	Intermittent
16	Passenger's door module(PDM)		✔
17	Headlamp control module(HCM)		✔
18	Restraints occupant classification system module(OCS)		✔
19	Keyless vehicle module(RFA)		✔
20	Front control/display interface module (high level display front)(FCDIM)		✔
21	Rear Heating ventilation and air conditioning control module(RHVAC)		✔
22	Restraints control module(RCM)		✔
23	Audio front control module(ACM)		✔
24	Satellite audio unit module.(SRM)		✔
25	Transfer case control module(TCCM)		✔
26	Driver's door module(DDM)		✔
27	Audio amplifier module(AAM)		✔
28	Parking brake control module(PBM)		✔
29	Parking assist control module(PAM)		✔
30	ABS control module(ABS)		✔
31	Gear shift module(GSM)		✔
32	Chassis control module(CHCM)		✔
33	Transmission control module(TCM)		✔

Remark:

\*This report is only responsible for the results of this detection: