

Bank 1	0-10%	11-20 %	21-30%	31-40%	41-50%	51-60%	61-70+ %		
0-1000 rpm	3.9	1.2	(2.7)	(0.5)	2.3				
1001-1500 rpm	(1.5)	(3.5)	4.9	3.6	5.6	6.3			
1501-2000 rpm	(0.3)	(1.1)	2.3	5.0	4.6	5.2	3.9		
2001-2500 rpm	0.0	0.1	1.6	3.0	3.6	6.6	3.6		
2501-3000 rpm	1.6	(6.6)	0.5	2.3	2.9	4.7	2.3		
3001-3500 rpm				6.3			0.0		
3501-4000 rpm			0.8	4.7	0.0	(0.8)	0.0		
4000+ rpm					6.3				
Bank 2	0-10%	11-20 %	21-30%	31-40%	41-50%	51-60%	61-70+ %		
0-1000 rpm	6.3	(4.6)	(5.5)	(0.5)	(3.1)				
1001-1500 rpm	(4.0)	(9.6)	(0.9)	(1.8)	(0.2)	2.3			
1501-2000 rpm	(0.1)	(3.8)	(1.5)	0.1	1.7	2.1	2.7		
2001-2500 rpm	0.1	(0.1)	(0.2)	(0.0)	2.3	2.0	2.1		
2501-3000 rpm	(1.2)	(6.3)	(2.5)	(0.7)	2.9	5.1	7.0		
3001-3500 rpm				4.7			0.0		
3501-4000 rpm			0.8	2.0	(1.6)	(3.1)	0.0		
4000+ rpm					5.5				