

Ford part numbers and prices for Jaguar 4.0L Tensioner replacement

PART NUMBER		QTY	LIST PRICE	YOUR COST		
1	2W9Z-6268-AA	CHAIN	2	\$47.90	\$95.80	Primary
2	2W9Z-6268-BA	CHAIN	2	\$20.51	\$41.02	Secondary
3	2W9Z-6L266-AA	TENSIONER	2	\$32.55	\$65.10	Primary
4	2W9Z-6L253-AA	TENSIONER	2	\$21.99	\$43.98	Primary
5	2W9Z-6K254-BA	TENSIONER	1	\$53.42	\$53.42	RH Secondary
6	2W9Z-6K254-CA	TENSIONER	1	\$59.16	\$59.16	LH Secondary
7	2W500301-S300	SCREW	4	\$1.50	\$6.00	Short bolts for metal tensioners
8	2W9Z-6K297-AB	GUIDE	2	\$17.60	\$35.20	
9	3W4Z-6584-AB	GASKET	1	\$51.47	\$51.47	FelPro are even less
10	3W4Z-6584-BB	GASKET	1	\$51.75	\$51.75	
11	2W9Z-6700-AA	SEAL AS	1	\$11.48	\$11.48	
12	2W9Z-6020-AA	GASKET	1	\$5.77	\$5.77	
13	2W9Z-6020-BA	RING	1	\$3.80	\$3.80	

August 2008 \$523.95