



All

DATE 11/96
Amended 06/04

6-47

SERVICE

ADMINISTRATION BULLETIN

Transit Isolation Device –
Return to Jaguar

MODEL	All
VIN	

Issue:

It has come to our attention that not all dealers are returning the battery isolation devices.

Dealers are reminded that it is a requirement to return ALL battery isolation devices once they have been removed from the vehicle as part of the Pre-Delivery Inspection Sheet - All Models.

Action:

Use carton JAG 6991 to return the transit isolation devices to Jaguar with the regular warranty part return shipment.

Relays are to be packed 50 to a dedicated returns box, part number JAG 6991 (available free of charge from Unipart through JPC).

No Part Return Edit Slip will be issued, but a dealer is required to fill out a Battery Transit Relay Returns Form and place a hard copy in the returned box with the displaced relays. The dealer should mark the outside of the box "Battery Transit Relays" and the quantity contained inside.



Battery Transit Relay Returns Form

Battery Transit Relay Returns Form

From:

Dealership Code:

Shipping Date:

Market/Country:

Quantity:

Battery Transit Relay Returns Form

From:

Dealership Code:

Shipping Date:

Market/Country:

Quantity:

Battery Transit Relay Returns Form

From:

Dealership Code:

Shipping Date:

Market/Country:

Quantity: