

Connector: **C23-A**

**CONNECTOR HOUSING NOT SERVICEABLE**

Description: **ICE harness to instrument panel harness**

Location: **Beneath center console LH side**

Qualifier:


ASSEMBLY

Part No.: **CASSY**

Colour: **NO COLOUR**

Cavities: **1WY**

Harness: **TELEMATICS HARNESS**



**Wire Chart**

CAV	CSA	COL	CCT	DESTN
1	0.5	VT	J3KAB	C44-L
2	0.5	VT	J3KAB	C44-L