


RealGauge Install



Wood Trim Removed

RealGauge Install




3 Temperature Stickers Added (215 not straight but could re-position it once in place)

RealGauge Install




Ribbon Connector disconnected from the main circuit board

RealGauge Install




Velcro, Speaker and new Circuit Board Added

RealGauge Install



Close up of the new Circuit Board installed

RealGauge Install



10 way Connector installed on the new Circuit Board

RealGauge Install



RealGauge showing engine coolant temperature

RealGauge Install



OBDCOM showing engine coolant temperature