


Connector: **PI051**

**CONNECTOR HOUSING NOT SERVICEABLE**

Description: **Ground point**

Location: **Front of engine - center**

Qualifier:




Part No.: **YPG900360**

Colour: **TIN PLATED**

Cavities: **1WY**

Harness: **PETROL ENGINE V8 N/A HARNESS**



### Wire Chart

CAV	CSA	COL	CCT	DESTN
1	2.0	B	(V_6)/(V_8)	S/JOINT PIS31